

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 36 N.R. 25 W


Menominee COUNTY

DESCRIPTION OF CORNER Section corner for sections  $\frac{10}{11}$   $\frac{15}{14}$

CORNER MONUMENT 1" Iron pipe with 4" Aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/29/67, Frank J. Bray

WITNESSES TO CORNER..... 12" R. Pine (S11)(NBT) N 20° E, 21 Links



13" R. Pine (S15)(NBT) S 70° W, 24 $\frac{1}{2}$  Links

AND

CIRCLE CORNER REGISTERED

### DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Placed at woodpost with an old wood post down found rotted point of old wood post along side newer post. ~~Along side newer post. ~~mark~~~~ Blazed spruce facing post. No original evidence found.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 11/8/67  
REGISTERED LAND SURVEYOR