

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T.36.. NR.. 28.. W

M e n o m i n e e COUNTY

DESCRIPTION OF CORNER Witness corner for 1/4 Corner between Sections 26 and 27

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 7" Cedar (W. C. NBT) N 54° W 32 Links

7" Cedar (W. C. NBT) N 40° E 18 Links

Monument marked = (W. C. 26/27 1/4 S. 1.36 chains.)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from two cedar B.T.'s bearing N 21° E 17 links and N 75° W 16 Links Both stps have been cut. Lower blaze and notch remains. Found by C. Limpert D. F. Corner lies 30 Links N. of lake edge. Note: This is a witness corner. True 1/4 corner lies 1.36 chains south in lake.

Corner was placed and witnessed August 11, 1960 with C. Limpert and J. Bastian.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 9/14/60