

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 37 N. R. 25W


Menominee COUNTY

DESCRIPTION OF CORNER Section corner for sections $\frac{27}{26}$ $\frac{34}{35}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8/9/68, F. J. Bray

WITNESSES TO CORNER..... 8" W. Pine (S. 27) (NBT) N 65° W, 18 links



7" Hemlock (S. 26) (NBT) N 49° E, 25 links

10" W. Pine (S. 35) (NBT) S 28° E, 12½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from old wood post and older rotted and down wood post. Old blazes on trees near. Stumps in area badly rotted. No original evidence found.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 8/28/68
REGISTERED LAND SURVEYOR
Frank J. Bray