

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. _____	N. _____ S., R. _____ E. W.	_____
2. PROPERTY CONTROLL- 30 _____, T. _____	37N N. _____ S., R. _____ 27 E. W.	14, 15
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____	N. _____ S., R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 12/10, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
- 14 - S 1/16 Corner East boundary Section 30; not previously established.
 - 15 - W 1/16 South side Section 30; not previously established.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 14 - Set M.P.O.L. between the East 1/4 Cor. and the S.E. Section Corner of Section 30.
 - 15 - Set by single Prop. Mea. between the S. 1/4 Corner and the S.W. Section Corner of Section 30.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 14 - 1" pipe, 4" aluminum cap; 8" R. Maple S32°E 61.8'; 10" Cedar (stump) S4°W 25.2'; 8" R. Maple N54°W 52.7'; W. Birch N11°W 97.9'.
 - 15 - 1" pipe, 4" aluminum cap; 4" Cherry N06°W 44.8'; 5" Spruce N47°E 98.4'; 5" Balsam N71°E 111.4'; 1" pipe S68°E 19.8'.

SIGNED BY David B. Babbitt DATE 12-16-82

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____