SURVEY & REMONUMENTATION

JAN 0 9 2001

SECTION

Signed by

Surveyor's Michigan License No.

| Approved by Menominee County |
|---|
| Land Survey Remonumentation |
| Peer Group Under Act 345 of PA. Of 1990 On 2000 |
| PA. Of 1990 On 26/20 20 CO |
| MARAIN PIS |

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Chairman MENOMINEE Located In: Corner Code # Bk. 6 Ps. 202 (County) T38NR 26W 1. Public Land Survey RECEIVED FOR RECORD 28 DEC 2000 2:31:31 PM R 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 5. Private Claims 2 3 William Lenca Sep. 05 in a field survey on do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the 5 United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, 7 recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded 9 on this certificate. 10 11 13 A. Description of original monument and accessories and/or subsequent restoration: Original Survey by George Adair - B.T.'s - W. Birch - N07.5°E - 21 lks; Tamarack - S21°W - 18 lks. All original evidence for this corner has been destroyed by County Road improvements. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We found a Railroad Spike in the centerline of County Roads East - West and South and in line with an old fence line running North. My private field notes indicate that we set a P.K. Nail at this location in a 1985 Survey and later replaced the P.K. with a Railroad Spike. This position fits very well with measurements to Corners 1/2 mile North, 1 mile East, 1/2 mile West and 1/2 mile South, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: Trans Lin 8" dia, Tamarack N050E 34 82 feet Scr. NBT 11" dia. Cedar N640E62.29 feet Scr. NBT 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" S350E 37.62 feet 1.0' E. of Co. Rd. Sign 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" S490W 80.31 feet 1.0' NE of 9" dia. Poplar Metal Survey Sign Post North 33.6 feet NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Sept. 8, 2000

Date