Approved by Menomines County
Land Servey Rememberships
Peer Group Hader Act 246 Of

AND CORNER RECORDATION CERTIFICATE	
Filing Requirement of Act 74, Mich. P.A. 1970	

	Fili	ng Requirement of A	ct 74, Mich. P.A. 19	970	Chair			-
or corners in			1					
MENOMINEE	Located in:	Corner Code#			22 34	95	: <u>:::</u>	
(County)			ļ		프로 플로 프로	330	邑	
1. Public Land Survey	T39N R T R T R	27W	<u>o</u>			10 27 PH	ECCHYCO FOR A	
2. Property Controlling in Section 3. Miscellaneous Property in Sec.	S TR S TR S TR S TR			Roniets	of Deeds S	Ç;; √32	NE CONTI	mbe
Froberty in oco.	<u> </u>		<u></u>	1/egioti	, or product			
on this certificate.	_, in a field survey or gan P.A. of 1970, the collection of rules therefore as requisitions, Bureau of Land din lines 3, 4 and 5 above a Decree of a Court below:	n Aug. 16, 19 95 of mer points mentioned in line ired in the current manual of Management or by a decree we were in conformance with to f Law; established, re-endown and range, may be re-	io hereby state that under es 1 and 2 above were in survey instructions of the of a Court of Law and /or the rules of the Michigan stabilished, monumented, conded	6 -18	D E F 5	G H I	1 J K	
A Description of original m	nonument and access	ories and/or subsequent	restoration:					

1852: Original Survey by Harvey Mellen - B.T.'s: Cedar, 12" - N13°W - 16 lks; Cedar, 20" - S03°E - 27 lks. All original evidence for this corner has been destroyed by county road improvements.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In a 1995 survey of Section 27, T39N-R27W, we set this corner in the centerline of a North - South County road, in line with an ancient fence to the West and in line with an ancient fence running East from the end of an old farm lane. The old farm lane runs East approximately 660', and the old fence continues East from the center of the lane. There is also an ancient fence occupation at the 1/16 line south of the corner position. The 1/16 fence runs East and West from a position which would split the distance between the E1/4 Corner of Section 27 (subject corner) and the SE Corner of Section 27. Placing the 1/4 corner in this location causes the North 1/2 mile to measure 2710.46 feet and the South 1/2 mile to measure 2539.83 feet, however placing the corner equidistant would upset long standing and substantial lines of occupation. We therefore accepted the occupied location for corner I-10 as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 12" dia. Tamarack	580°E	37.68 feet	@ S. Gate Post
	577°W	131.30 feet	Scr. NBT
5/8" x 24" Iron Rod/plastic cap marked MI 26461/WI 1569	West	33,00 feet	Scr. NBT
7" dia. Tamarack	N40 ⁰ W	71,48 feet	SCI. ND1
Metal Succey Sign Post	S80 ⁰ E	38,0 feet	

SED LAND SUP

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

A	_	A STATE	TE OF MICA	EARLE TO THE PARTY OF THE PARTY	
Signed by Ll Mann		*	WILLIAM	· * #	Date _
Surveyor's Michigan License No	26461	*:	LAND	*	
	Ę	gra.	No. 26461		APPROVED BY

Dec. 14, 1995

PPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 16 REVISED MAY 14,11 REVISED JAN, 1 REVISED OCT., 11