

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T39-40 NR 25 W

M e n o m i n o e . . . . . COUNTY

DESCRIPTION OF CORNER ~~Section corner common to Sections 5, 6, 31, 32~~ . . . . .

DESCRIPTION OF CORNER MONUMENT . . . 1" Pipe with 4" Brass Cap . . . . .

WITNESSES TO CORNER 10" Hard Maple (S 32 NBT) . . . . . N 88° E 11 Links . . . . .

12" W. Birch ( NBT ) . . . . . N 27° W 10 Links . . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced at old Cedar post set in fence corner. Found down Cedar with axe marks, bearing S 20° W 31 Links. Found by C. Limpert in 1941.

Corner was placed and witnessed August 25, 1960 with C. Limpert, D. F. and J. Bastian.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/14/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler