

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Menominee COUNTY


T 40 N R 25 W

DESCRIPTION OF CORNER Section corner for Sections <sup>30/29</sup> 31/32

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4/29/71 F. J. Bray

WITNESSES TO CORNER..... 10" Cedar (S. 29) (NBT) N 50° E, 10.7'



6" Cedar (S. 31) (NBT) S 40° W, 10.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from original B.T.'s. Tamarack to northeast is a dead leaning stub with scribe marks on upper face. Cedar to the southwest is a rotted stump in proper bearing and distance. Several blazed trees near.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Frank J. Bray*  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

6/8/71

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68