## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	COUNTY
	T <u>40 N</u> R's 25 & 26 W
DESCRIPTION OF CORNERSection corner for Sections	THON <u>25/30</u> THON R26w <u>36/31</u> R25w
CORNER MONUMENT 1" iron pipe with h" aluminu	ım cap
DATE MONUMENT PLACED AND WITNESSED 5/10/71 F. J. Bra	<b>y</b>
WITNESSES TO CORNER 18" Hemlock (S. 25 NBT) N 15	οw, 14.9'
2½" W. Pine(S. 31 NBT) S 27	<mark>7<sup>0</sup>ь, 20,7</mark> ;
TAON R25W AND	
CIRCLE CORNER REGISTERED	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was reestablished by placing to conform with land calls found in
the original notes. Distance to the 1/4 corner to the north checks well.

Distance to town corner to the south is short. Swamp edges to the east and west
check fairly well. No original evidence was found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED REGISTERED LAND SURVEYOR

DATE 6-23-7

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68