

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T~~41-42~~ NR 25 W.

M e n o m i n e e COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 6 and 31

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 9" Cedar (1/4s NBT) S 32° W 15 Links

9" Cedar (1/4s NBT) S 78° E 08 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from one Cedar B.T. bearing N 18° E 18 Links B.T. is a 4' high stump. Scribe marks in good condition. This corner has been perpetuated by Sawyer Stoll Timber Company.

Corner was placed and witnessed August 12, 1960 with E. Dahlvik, Sawyer Stoll Timber Company and J. Bastian, Ass't D. F.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/14/60
REGISTERED LAND SURVEYOR
Billy D. Buckler