

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

MENOMINEE Co.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. _____ N. S., R. _____ E. W.		
2. PROPERTY CONTROLLING IN SECTION <u>25</u> , T. <u>41N</u> N. S., R. <u>25W</u> E. W.		<u>2, 1.</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 2, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- 1) West 1/16 cor. on the north sec. line of Sec. 25. Not previously est.
- 2) East 1/16 cor. on the north sec. line of Sec. 25. Not previously est.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 1) Set M.P.O.L. between the N $\frac{1}{4}$ cor. and the NW sec. corner of Sec. 25.
- 2) Set M.P.O.L. between the N $\frac{1}{4}$ cor. and the NE sec. corner of Sec. 25.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|--------------------------------------|--------------------------------------|
| 1) D.N.R. Mon. | 2) 1" pipe, 4" alum. cap. |
| 7" cedar - N51° E - 16.75 | 5" cedar - S30° E - 12.4' |
| 6" cedar - S45° E - 31.25' | 5" cedar - N67° E - 28.0' |
| 7" cedar - N65° W - 11.0 | 4" cedar - S86° W - 4.2' |
| 9" w.birch - S37° W - 9.2' | 6" cedar - N69° W - 34.4' |
| Decl. = 8° West | Bearings shown are compass readings. |
| Bearings shown are compass readings. | N88°W - Bearing of random line. |

SIGNED BY

David B. Babbitt

DATE

1-16-85

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY