

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T~~41-42~~ NR . . 26 . . W

Monroe COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 1 - 36

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 4" B. Spruce (1/4s NBT) N 23° E 10 Links

4" B. Spruce (1/4s NBT) S 68° W 38 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two section corners. No evidence of original corner. Corner lies 25 links west of old logging road.

Corner was placed and witnessed August 12, 1960 with E. Dahlvik and J. Bastian.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/14/60
REGISTERED LAND SURVEYOR
Billy D. Buckler