DEC 27 1993

PARTY DE CONTRACTOR OF THE

Lot No. Private Claims _

LAND CORNER RECORDATION CERTIFICATE

San Marie 12 - Ald I am a 2 the 1 th	
For corners in	Filing Requirement of Act 74, Mich. P.A. 1970

UBER 383 PAGE 437

Missaukee Located in: Corner Code ## MISSAUKEE COUNTY MICHIGAN жоково **ДЕС** 1 6 1993 — М. T 21N R 7W **Public Land Survey** T _____ R ___ T _____ R __ T _____ R __ ___ T ____ R __ **Property Controlling** S ____ T ___ R ____ in Section S ____ T .___ R __ Miscellaneous Register of Deeds Stamp & File Number Property in Sec.

I, J. Dean Geers , in a field survey on December 13 , 19 93 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

__ , Recorded Plat __

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10 11
- Description of original monument and accessories and/or subsequent restoration:
- I-13) 1837 GLO Section post by John Brink, Deputy Surveyor

Hemlock 12 N 19° W 7, Hemlock 11 N 58° E 28

- 1912 Beuthien survey in Section 34: Corner perpetuated by Richardson: C.F. post N 46°E 71
- I-13) 1993 Granger survey, Liber S-3, page 179-180: Set 1/2" Iron and cap
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - I-13) Section corner common to Sections 34 and 35

Found Granger Iron of record per Liber S-3, page 179-180 but it was not utilized in this survey.

Found and restored the Section corner common to Sections 34 and 35 from the 1912 Beuthien survey. Found a piece of crockery at the corner position which was based on the retracement of the 1912 Beuthien survey. The corner falls ± 12 ' South of the centerline of the East-West road and $\pm 7'$ West of the centerline of the road to the North. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - Found a piece of crockery which was broken due to excavation. I-13) Set 1/2" x 36" Iron and Missaukee County monument in the center of the broken piece of crockery

N 23° W - 53.46 - Corner fence post N 11° W - 85.57 - 10" Poplar

N 38° E - 97.85 - Power pole S 26° E - 104.54 - 10" White Pine

Peer Group Reviewed and Approved

J. Dean Geers, Missaukee Co. Representative

Signed by Om Dun	Date _	12/15/93
Surveyor's Michigan License No. 33977		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SU