LIBER 333 PAGE 427

JAN 1 9 2000

SECTION

For corners in

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1339

Missaukee County Located In: Corner Code # (County) T 22N R 05W 1. Public Land Survey C-13

MISSAUKEE COUNTY MICHIGAN

Т

1200RDED DEC 0 9 1999 4/JM.

Caulyn Flore


2. Property Controlling Т in Section 3. Miscellaneous Т

Register of Deeds Stamp & File Number

4. Lot No. ______, Recorded Plat _____

5. Private Claims _

in a field survey on <u>June</u>, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:



NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-13) 1837 GLO Section Post by John Brink, Deputy Surveyor. 12" Beech-N27E-6 lks, 11" Beech-N34W-45 lks. C-13) 1852 GLO Section Post recovered by A. Curtis, Deputy Surveyor. 10" Sugar-S23E-50 lks, 10" Beech-S50W- 12 lks. McBain Survey: Piece of iron, 10" Sugar-S23E-50 lks. C-13) 1907

1912 Beuthien Survey; Iron and stone, 6" Maple-N31E-205 lks, Boulder-N29½E-92 lks. C-13)

C-13) 1915 Beuthien Survey; No corner witnesses. C-13)

County Survey Notes. 10" Sugar-S23E-50 lks, 10" Beech-S50W-12 lks.

C-13) 1938 Schaaf Notes: Found corner.

C-13) 1972

McClung LCRC, Liber 1, Page 89; Found rod and cap #14099. 20" Maple-N52W-73.80', 23" Oak-N45W-47.0' C-131 1978

Cavanagh Survey, S-1, Page 396; Found 1/2" bar and cap. 20" Maple-N52W-73.80', 23" Oak-N45W-47.0'

Cavanagh LCRC, Liber 1, Page 550; Found 1/2" bar and cap. 20" Maple-N52W-73.80', 23" Oak-N45W-47.0' Robinson Survey, S-3, Page 89; Found 1/2" bar and cap. 20" Maple-N52W-73.80', 23" Oak-N45W-47.0' C-13) 1979

C-13) 1991

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Section corner common to Section 31, T22N, R5W, Section 32, T22N, R5W, Section 6, T21N, R5W and Section 5, T21N, R5W. Found ½" rebar and remains of cap as recorded in Liber 1, Page 89. Corner is in centerline intersection. This corner is accepted as the best available evidence of the position of the original corner.
- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - Found ½" rebar and remains of cap. Replaced rebar with ½ "x18" rebar and Missaukee County Monument C-13) in monument box.

N46W 47.71' Set nail in northeast face 30" oak **N60W** 74.46 Set nail in south face 30" maple 74.99' S47W Set nail in southeast face Powerpole S64E 105.041 Set nail in south face Powerpole N50E 50.71 Set nail in northwest face Telephone Riser pole

Peer Group Reviewed and Approved

J. Dean Geers, Missaukee Co. Representative

Surveyor's Michigan License No. 33977