LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Missaukee (County)		Located In		Corner Code #	
 Public Land Survey Property Controlling in Section Miscellaneous Property in Section 	S 35 S 35 S	T T T T T T T		4 8	Register of Deeds Stamp & File Number
4. Lot No: 5. Private Claims:					A B C D E F G H I J K L M 2 - 6 - 5 - 4 - 3 - 2 - 1 - 1
I, <u>Craig W. McVean</u> , in a firequirements of PA 74, Mi and 2 above were in conforthe current manual of sul Interior, Bureau of Land Macorner points mentioned in of the Michigan Board of established, re-established	chigan PA ormance with rvey instruct anagement lines 3, 4 a f Land Su	of 1970, the regulations of the corrections of the	the corner points ons and rules the the United State oree of a Court over were in conform by a Decree	mentioned in lines 1 erefore as required in s Department of the of Law and/or that the rmance with the rules of a Court of Law;	3 4 7 8 9 10 11 12 5 6 18 -19 20 -21 -22 -23 -24 9
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.					10 30 29 28 27 26 25

- A. Description of original monument and accessories and/or subsequent restoration:
- 4 1913 CSR E. A. Beuthien Sec. 35 Petition Survey -
 - Cedar Stake 4" x 4"; Elm 11" N77°W 39

 2003 Unrecorded Survey North Central Survey inc. Proj. #03065 – L.L. Cavanagh – Set ½" bar in abandoned E-W Rd Bed and 26'± West of remains of N-S Wood post fence running South.
- 8 1913 CSR E. A. Beuthien Sec. 35 Petition Survey -Cedar stake; WPS 30" S20°E 80
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- $\underline{4}$ NW 1/16 Cor. Sec. 35, T22N, R5W Based on retracement of Beuthien survey dug 8' E & W x 3.5' N-S area in Old E-W Road Bed looking for stake but nothing found. Set 2" Alum. Cap on 5/8" x 34" rebar in centerline of old E-W Road Bed per Standard BLM procedure in dug area.

Reference Pt. - Fd. 1/2" CIR # 17614 is N86° 22"E 10.86' of '4'. 1/2" CIR based on rejected corner positions and is not utilized as '4' in this survey.

- 8 CW 1/16 Cor. Sec. 35, T22N, R5W A newer looking 3/4" iron pipe was found at an old fence intersection N, S & W - 16' westerly of the calculated position. Dug at pipe position for evidence of cedar stake but nothing found. From the pipe at Beuthien's Bearing and distance a fallen W. Pine was found. Being that Beuthien called for a stump didn't feel 3/4" pipe was conclusive evidence of his position. Thus set 2" Alum. Cap on $5/8" \times 34"$ rebar per Standard BLM procedure.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 4 Stamped 2" Alum. Cap on 5/8" x 34" rebar w/ cobble stone around. Set Blue Carsonite Post with loc. tag 1' NE N86°22"E 10.86' to Ref. Pt. - 1/2" CIR #17614. N15°W 21.97' to N & T in W. side Tri 16" R. Maple N65°E 6.30' to N & T in N. side 4" Oak $S29^{\circ}W$ 46.65' to N & T in E. side 12" W. Oak N77°W 9.31' to N & T in S. side 2" W. Pine
- <u>8</u> Stamped 2" Alum. Cap on 5/8" x 34" Rebar Set Blue Carsonite Post with loc. tag 1' NW East 9.5' to centerline Overhead Power Line S78°W 15.68' to fd. $\frac{3}{4}$ " iron pipe at Fe. Cor. remains. N87°W 22.97' to set N & T in N. side 9" R. Maple S19°E 31.02' to set N & T in E. side P.P S85°E 52.63' to set N & T in S. side 6" W. Oak N64°E 59.25' to set N & T I n SE side 7" Oak

39088

Date:

OF MICHIGA CRAIG W. McVEAN 3908L Persendi Pevised Ja Ped O **PROFESSIONAL**

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SU

ised Jan. Revised Oct. 1995