JAN 27 1999

For corner

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

#	12	7/

LIBER 318 PAGE 160
MISSAUKEE COUNTY MICHIGAN

RECORDER APR. 9 1998 PM aulyn Flore

Register of Deeds Stamp & File Number

Missaukee {County}	Located In:	Corner Code #
1. Public Land Survey	T_23N_R _5W_	M-7
	TR	
Property Controlling in Section Miscellaneous Property in Sec.	TR STR STR STR	

Private Claims _ I, Craig W. McVean, in a field survey on <u>Dec. 4</u> 19 <u>96</u> do

hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

4. Lot No. _____, Recorded Plat _____

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	В	С	D	E !	E, 0	1 2	(ι .	I K	L	M
1 [T										
2 -	6-		5	- }-	4	;۔۔	·		2-	i	-1
3 —	- -	4	1		}_	_		<u> </u>		<u> </u>	\vdash
4		-	- <mark>8</mark> -	+-	ا 9-—	1	o	1	1	1	2-
5	+	+		-	-		_			-	\dashv
6	-1 8-	+	-17-		6	_1	1 5 I	<u> </u>	4-	_1	3
7 -	+			-	├	<u> </u>	<u> </u>				-4
8 -	 -1 9-	_	-s'υ− 	1-2	 1	2	 2	2	3—	2	4_
9	+			-	-		_				-
10	.3 0		_2 [†] 9_	+-2	! 8	2	7	2	6-	2	5
11	+-	+		 	-	-	_		_		\dashv
12	3 ['] 1–	+	-3 2-	1-3	3 	3	4— 	3	5—	3	6-
	- 1	- 1	1			ı					

OF MICHIGA

A. Description of original monument and accessories and/or subsequent restoration:

M-7 - GLO - Set Post - J. Brink - 1830 Spruce 7" S76°W 13L. W. Pine 8" N71°W 17L. - Miss. Co. BK. 24, P. 56 & 61 - FND. Old Cor. in N. Edge Tam. Swamp - Old B. OK - 1913 N.B. - WPS 14" N61°E 108L. - YPS 16" S54.5°E 130L.

LCRC #572 - Miss. Co. - FND. 3" Sq. X 30" Cedar Stake - J. Wilcox - 1979 N 60°E 3" S. Pine 10.45' S45°E 6" S. Pine 14.14' \$18°E 12" S. Pine 21.7" \$20°W 4" \$. Pine 25.1" W. P. Stump 16" \$54°E 130L. (1913 OBT)

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-7 Townline Sec. Cor. common to Sec. 13 & 24 T23N, R5W & Sec. 18 & 19 T23N, R4W Found capped 1/2" x 18" Iron Rod and 3" x 2.5' Long Wood Post with point in swamp per record LCRC. Also find remains of both 1913 BT's. Monument accepted as a careful and faithful perpetuation of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-7 - Replaced Iron Rod & Wood post w/4" Department of Natural Resonant Set Carsonite Post SSE 2'. Reset Iron Rod & Wood Post on N. Side S54°E.86.40' to Set Nail in CL. 16" + Y. Pine Stump (OBT) N61°E 72.14' to Set Nail in CL. Rotted Remains of Pine Stump (OBN57°E 10.45' to Set N&T in S. Side 9" J. Pine (JW) S50°E 14.14' to Set N&T in SW Side 11" J. Pine (JW) S18°W 21.70' to Set N&T in W. Side 14" J. Pine (JW) S76°E 51.54' to Set N&T in SW Side 14" R. Pine scribed "XBT" S34°E 64.33' to Set N&T in NE Side 13" W. Pine scribed "XBT" S79°W 58.53' to Set N&T in N Side 2" R. Pine Signed by	e as memorial.
Surveyor's Michigan License No. 34088	