## JAN 1 9 2000

SECTION

## LAND CORNER RECORDATION CERTIFICATE

LIBER 330 DUAY 1-24

Ear	COMPARE	in

_	Filing Requirement	nt of Act 74, Mich. P.A	1. 1970 AGE 1977		
For corners in			ch con		
Missaukee	Located In:	Corner Code #	# 1320		
(County)			MISSAUKEE COUNTY MICHIGAN		
1. Public Land Survey	T <u>24N</u> R <u>5W</u> TR TR	<u>M-1</u>	permanen Allie 1 9 1000 BON		
Property Controlling in Section Miscellaneous Property in Sec.	TR STR STR STR STR		Register of Deeds Stamp & File Number		
4. Lot No, Re 5. Private Claims			2 -8 -5 -4 -3 -2 -1 -		
I, <u>Marvin E. Myers</u> , in a field 74, Michigan P.A. of 1970, the regulations and rules therefore Department of the Interior, Bu corner points mentioned in line	d survey on <u>March</u> , 19 <u>99</u> do hereby state corner points mentioned in lines 1 and 2 as required in the current manual of survey areau of Land Management or by a decree of es 3, 4 and 5 above were in conformance with ecree of a Court of Law; established, re-established,	above were in conformance instructions of the United State of a Court of Law and for that the rules of the Michigan Bo	with 5 ates 6 18 17 16 15 14 13 the 7 oard 8 19 20 21 22 23 24		
found as expressed below.	2 corners, all in the same town and		10 30 29 28 27 26 25		

A.	Description of	Foriginal monument and	d accessories and/	or subsequent	restoration:
----	----------------	------------------------	--------------------	---------------	--------------

G.L.O - 1839 John Brink, DS Mon -- Post

Marcus Schaaf 1940's Mon: Iron Set

Wit: 10" B. Oak N66°W 10 lks.

10" W. Oak N38°E 20 lks.

LCRC L1 P 199 Missaukee Co. Records Sept 17, 1974 Herbert L. Fluharty #18223

G.L.O. - Aug 1852 Geo. H. Cannon, DS

Mon - Post

Wit: None given

Mon - 1 1/2" pipe

Wit: 14" Oak \$72°W 59.85

15" Oak S44°E 58.00

8" R. Pine N28"E 69.75

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Schaaf 1 1/2" pipe in concrete. Found 18" Norway N35°E 69.64

Accepted pipe as the best available evidence of the position of the Originial Corner. Replaced pipe with Standard Crawford County Monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon: Standard Crawford County Corner 0.5' below surface.

Wit: Nail E. side 18" Norway N35°E 69.64

Carsonite Post N67°E 46.26

Nail S. side 16" Twin Maple S55°E 74.84

Nail N. side 7" B. Oak S76°W 66.86

annumitikitikit MYERS POFESSIONA RVEYOR No. 31600 OFESSIONA WILLESS!

Peer Group Reviewed and Approved

J. Deary Geers, Missaukee Co. Representative

Date June 1, 1999

Surveyor's Michigan License No. 31600