## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

	T. 24 N.R	7 W Kalkas Missau	
DESCRIPTION OF CORNER 1	/4 Corner common to Section	ns 6-31	
CORNER MONUMENTS	et 1" pipe with 4" aluminum	ı cap	
DATE MONUMENT PLACED AND	WITHESSED <u>May 3, 1966</u>		
WITHESSES TO CORNER			
	9* R. Pine	S 86 E	73•31
+	Twin 12" R. Pine	s 66 W	6h•h•
CIRCLE CORNER REGISTERED	AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Found 1" pipe with concrete cylinder at corner as established in early survey by County Surveyor. One old NBT stump in place, and remains of both probable USBT stumps.

SURVEYOR'S SEAL

SIGNED SULLEY DATE May 6, 1966

REGISTERED CAMP SURVEYOR \$10068