LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 24 N., R. 7 W.	F-8; H-8
2. PROPERTY CONTROLLING IN SECTION 21	,T. 24 N., R. 7 W.	8
2. ~~MISCELLANEOUS~~ 34	,T. 24 N., R. 7 W.	10
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on February 27, 19 80, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

8			10		
Drove 5/8" x 36" rerod w/RLS cap			Set 5/8" x 36" rerod (flush)		
8" Oak	S20°E	54.5	6" Maple	S50°W	39.5
4" Maple	S10°W	26.4	4" Maple	N59°W	44.4
9" Maple clump	N10°W	39.6	4" Maple	N11°W	56.8
Set ced. post w/loc tag N		33'	N-S fn.	E	20'±
			Set ced. post w/loc tag W		16.5

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-8 Set ctr. of Sec. 21 per std. B.L.M. instructions; at inter. of 1/4 lines. Cor. falls in approx. ctr. of E-W gravel rd.

H-8 Set ctr. Sec. 22 per std. B.L.M. instructions; at intersection of 1/4 lines. Cor. is in approx. line w/fn. to West and 18'± east of N-S fn. line; also fn. line N, posts mostly down, is 18'± East.

8 Set 1/8 cor. per std. BLM insturctions. Cor. falls in approx. ctr. of E-W gravel rd. and is 62'± West of a fence to South.

10 Established S1/8 cor. on W line S-34 per std. BLM instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-8			H-8		
Drove 5/8" x 36" rerod w/RLS cap			Drove 5/8" x 36" rerod w/RLS cap		
5" Oak	S30°E	38.60	16" Maple	N60°E	45.0'
11" Oak	S50°W	39.47	4" Maple	S68°E	66.9'
16" Maple	N70°W	99.41	7" Maple	S39°E	56.4'
Set ced. post w/loc tag N		33'±	Set ced. post w/loc tag W		18'

SIGNED BY Carl F. Roser DATE 5-13-81

STATE OF MICHIGAN — CARL F. ROSER LAND SURVEYOR No. 12028 — REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

PIONEER TOWNSHIP
MISSAUKEE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET