

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 24 N.R. 8 W


Missaukee COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 7-8-17-18

CORNER MONUMENT Set 1" pipe with 4" Alum. cap below surface

DATE MONUMENT PLACED AND WITNESSED 4-17-67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

Maple clump N 76 W 68.4'

6" W. Oak N 16 E 88.3'

AND \_\_\_\_\_

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this area. Recovered corner as restored by Fargo Engineering Company in 1912 survey by Consumers Power. Fargo records indicate corner restored from U.S.B.T.s, two of which are in place.

SURVEYOR'S SEAL

SIGNED \_\_\_\_\_ DATE 5-24-67  
REGISTERED LAND SURVEYOR #10068