SURVEY & REMONUMENTATION

JAN 1 6 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			#1189
Missaukee	Located In: Cor	rner Code #	LIBER 314 PAGE 1263
(County)	Located III.	Tiel Oode #	LIBER OF PAGE 100
1. Public Land Survey	T_24NR8W TR	J-13	MISSAUKEE COUNTY MICHIGAN
2. Property Controlling	TR TR		2000 MON 1 0 1881 1 600
in Section	\$ TR		Carolyn Flore
3. Miscellaneous STR			Country Track
Property in Sec.	S TR	·	Register of Deeds Stamp & File Number
		_	
4. Lot No, Reco	orded Plat	·	ABCDEFGHIJKL
5. Private Claims			
			2 -6 -5 -4 -3 -2 -1 -3
J. Dean Geers , in a field survey onJune , 19 97 do hereby state that unc			
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of the corner manual of survey instructions of the current manual of survey instructions of the corner manual of survey instructions of the current manual of survey instructions of the corner manual of survey			in filllifilli
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan			Or 6 19 17 16 15 14 19
that the corner points mentione Board of Land Surveyors or I	ed in lines 3, 4 and 5 above were in con by a Decree of a Court of Law; est	iformance with the rules of the Michiga ablished, re-established, monumente	an 7
recovered, found as expressed i	below:	,	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			9
on this certificate.			10 -30 -29 -28 -27 -26 -25
			11
1			12 31 32 33 34 35 36-
A Description of original m	nonument and accessories and/or	subsequent restoration	13
	Quarter Section Post by John Brit	·	179E-21 Beech 10-N73W-47
J-13) 1888 County		n 35, T24N, R8W; Elm 7-N79W	V-89, Corner Fence Post-NE-42.2
	•		
			·
B. Description of corner ev	vidence found and/or method appl	ied in restoring or reestablishing o	corner:
			•
Corner is ±2' l	er common to Section 35, T24N, F North of centerline East-West road aithful perpetuation of the position	d and ±20' Easterly of fence line	; Found ½" Iron in Pipe ±3' deep. to North. This corner is accepted as
•		•	
	•		
:			
C. Description of monumen	nt for corner and accessories estab	lished to perpetuate locating the	position of the corner:
J-13) Found Pipe an	d raised with ½" Iron and Missaul	kee County Monument	
N65W 71.95	5 14" Twin Ash	•	Door Crown Devices and American
N70E 64.86 S65E 94.30			Peer Group Reviewed and Approved
S65E 94.30 S65E 110.4			Date: 10.22.97
		<u>}</u>	J. Dean Geers, Missaukee Co. Representative
	LE MONTHER MENTER		
	J. DEAN CEERS		
Signed by	LAND LAND	Date	10-82-97
Surveyor's Michigan License	No. 138 7 No.		
कुल्या व्यवस्थान क्षाप्रकार कार्यक्र विश्वस्थान क्षाप्रकार कार्यक्र विश्वस्थान क्षाप्रकार कार्यक्र विश्वस्	18 33977		
	CAND SULLE	FORM APPROVED BY MIC	CHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197