JAN 2 8 1999

Montmorency County Remonumentation Liber 00012 Page 0324

SECTION.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For comers in								
MONTMORENCY (County)	Located in: ALBERT TWP.	Corner Code #		M	TATE OF ONTMOREN econded	ICY COUN	4TY	
1. Public Land Survey		12-03-1998 13:37:04						
Property Controlling in Section Miscellaneous Property in Sec.	TR TR S TR S TR S TR			R	ARY JO G EGISTER (OF DEED		umber
						~1		
4. Lot No, Records 5. Private Claims	o Plat		-	A B C	DEF	G H	1 J	K L
V. F IIFOGO OTANTIO			-	2 - 6	_ 5 4 -		<u> </u>	- -
				3			$\vdash \vdash$	
requirements of P.A. 74, Michigan conformance with regulations and ru United States Department of the Intelligent that the corner points mentioned in Board of Land Surveyors or by a recovered, found as expressed below	P.A. of 1970, the corner pointles therefore as required in the prior, Bureau of Land Manage lines 3, 4 and 5 above were in Decree of a Court of Law;	its mentioned in lines 1 and 2 ai e current manual of survey instru- ment or by a decree of a Court of a conformance with the rules of t	bove were in ections of the Law and /or the Michigan	4 - 7 - 5 - 6 - 18 - 6 - 7 - 8 - 19 - 8	- 8 9- - 17 16- 20 21-	15	11	13-
	s, all in the same town and	range, may be recorded		9	-29 - 28	27	26_	25
on this certificate.	•			10 -30	-29 -2 9			
				12 31	_3233_	34	35	
				13			$\perp \perp$	
A. Description of original monu C-6 - 1/4 CORNER COMM	ION TO SECTIONS 1	7 and 18:						
June 1840 - Orig Post (Pg. 374) Corner C-	\	ason, DS + N38°E-1 S47°W-2 7 Ch. (374.22') No	Z LKS(14.	•22.1-0	napre		e La)	¢e)∙
NO LCRC OR ACT 132's has performed most of indicated that the passec. 18, therefore, Cobetween Corners C-5 a	the Surveys, in crcels located with cor. C-6, MP #18	both Sections 17 of thin these 2 Section MP #19 were neve	and 18, d ons, were r needed	over the period in and to h	past 20 to the i is know	years NW Cor ledge,	ner of the	es est
B. Description of corner	evidence.found and/or	method applied in res	toring or i	reestablish	Ing corne	r:		
C-6 - 1/4 CORNER COMM	ION TO SECTIONS 1	7 and 18:						
inspection of t	he area indicated	ents, to establish d, did not un-cove of the Original C	r any Coi	rox. loca rner or O	tion of riginal	Corne Witne	r C -(ss Ev	5, 7 i —
distance and on THIS CORNER WAS APPROFAITHFUL ESTABLISHMEN	n line, between Co OVED BY THE MON. NT OF THE POSITIO	N OF THE CORNER.	N JULY 2	8, 1998,	AS A CA			ıal
C. Description of monument for					_			
:-6 - 1/4 CORNER COMM RAN LINE FROM CO "C-6", MID-WAY	ORNER "C-5" to "C	-7" (Meas. 5186.50 LINE BETWEEN CORN	') - SET	CONC. MC	N. & RE	-MON C	AP @	
N.30°E 3 N.75°E 4	27.92' - Set S&T 49.31' - Set S&T	on SE Sd of 20" Oa on NW Sd of 20" Oa	k k					,
S.10°E 3 West 3	29.55' - Set S&T 28.35' - Set S&T	on W. Sd of 18" Oa on S. Sd of Pwr. P	ole #LW5	-5DB-1 (N	-S Pwr	Line)		
Corner is	± 7' NE of C.L. o	of 2-Track Drive on & Co. Re-Mon Cap					tacl	e Lak
Mandavil	1 0 Kma)	•	ly 28, 19	^	PPRC	DVE	D BY
igned by <u>+/WAV/UCA</u> iurveyor's Michigan License No.	25852				7			, •
MITAGYOLO MICHINGALL ELLENSE MU.				4	1.4B	JUL 2	: 8	98