SURVEY & REMONUMENTATION

FEB 0 6 1998

Montmorency County Remonumentation

Liber 00012 Page 0269

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| MONTMORENCY (County) | Located In: ALBERT TWP. | Corner Code =## | STATE OF MICHIGAN |
|--|------------------------------------|---|---|
| Public Land Survey | T 29N R 1E | (K-10) as Related to | MONTMORENCY COUNTY Recorded & Filed |
| • | T R T R | P. 4. 5 | |
| | T R | | 11-12-1997 09:40:56 |
| Property Controlling in Section | S T R S T R | | A. PANGAN-MCELROY |
| 3. Miscellaneous | S T R | - | REGISTER OF DEEDS Register of Deeds Stamp & File Number |
| Property in Sec. | S T R | | |
| 4. Lot No , R | Recorded Plat | | A B C D E F G H ! J K I |
| 5. Private Claims | | | 2 6 5 4 4 3 2 |
| | | | 3 |
| LEDENEDICK 1 KING | in a field suggest on home 10 | | 4 - 7 - 8 - 9 - 10 - 11 - 11 |
| do hereby certify that under req | uirements of P.A. 74, Michigan P.A | . of 1970, the corner points mention | ed 6 |
| | | nd rules therefore as required in t rtment of the Interior, Bureau of La | nd stolen M/C |
| | | er points mentioned in lines 3, 4 and of Land Surveyors or by a Decree o | 23-1-23-1-23-1-23-1-23-1-23-1-23-1-23-1 |
| Court of Law; established, re | | monumented, recovered, found | as * to I KING * |
| expressed below: | orners, all in the same town a | nd range may be recorded | PROFESSIONAL 4 |
| on this certificate. | | na rango, may bo roosrada | 31 HO32 34 35 |
| A Description of original | monument and accessories an | d/or subsequent restoration: | 25852 |
| K-10 - 1/4 CORNER COMMON | | droi subsequent restoration. | APOFESSIONAL ST |
| <u> </u> | | g 356) * N27W-22]k(14.52*); | 6" Spr P. * \$42E-29 lk(19.14')15" J. Pin |
| Apr. 1968 - Act 132 by N. | C. Caldwell, PS #12018 - N | o Cor Desc - No Wit - Not R | ecorded - (Şet Post thru Ice) und in "BIG WOLF LAKE" - Set ½" Iron Bar |
| | Sta | | High Ground and on Section Line. |
| B. Description of corner ev | | applied in restoring or reestabl | ishing corner: |
| | Henning Iron & Cap #2240 w | ith Broken Concrete Mon alo | APPROVED BY PEER GROUP |
| | | | IUN 2 0 97 |
| | | | L.G. |
| | | | · |
| Original Corner, as related. Description of monumer | ted to the Reference Monume | ent established to perpetuate locat | able evidence of the position of the ting the position of the corner: |
| | | | ocation - (Removed Broken Mon) |
| 36.90' North of sai N10E - 30.91' - Set N45E - 7.62' - Set | | Pine | a "REFERENCE CORNER" to said K-10 and is |
| N55W - 15.30* - Set | t S&T on NE side of 8" Oak | | e to tell what is at Corner. |
| Signed by 4 rederick | J. Kmg | Date | v. 6, 1997 |
| Surveyor's Michigan License | No. 25852 | | RM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, |