SURVEY & REMONUMENTATION

FEB 0 6 1998

Montmorency County Remonumentation

LAND CORNER RECORDATION CERTIFICATE iber 00012 Page 0259

| Enr corners in | Filing Requiremen | nt of Act 74, Mich. P.A. 1970 |
|--|--|--|
| For corners in SECTIO | N | STATE OF MICHIGAN |
| Montmorency (County) | | Corner Code ≠ MONTMORENCY COUNTY Recorded & Filed |
| ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | · | Vecouded # Liled |
| Public Land Survey | T 29N R 1E | M-12 M-12-1997 11:42:56 |
| | | .A-12 |
| | | A. PANGAN-MCELROY |
| 2. Property Controlling | ^ T ^ | REGISTER OF DEEDS |
| in Section | ^ | |
| 3. Miscellaneous | S R R | Register of Deeds Stamp & File Number |
| Property in Sec. | S R | |
| 4 Lot No | Recorded Plat | |
| 5. Private Claims | | A B C D E F G H I J K L |
| | | 2 - 6 - 5 - 4 - 3 - 2 - 1 |
| | | 3 |
| . Larry G. Beauregard | , in a field survey onMay 16 | 4 7 8 9 10 11 1-1-1 |
| do hereby certify that under re- | quirements of P.A. 74, Michigan P.A. of 1970 | O the corner points mentioned |
| in lines 1 and 2 above were in | n conformance with regulations and rule: | s therefore as required in the |
| | ructions of the United States Department of a Court of Law and/or that the corner point | Is most in part in lines 2. 4 and 5 |
| above were in conformance wi | ith the rules of the Michigan Board of Land | 1 Surveyors or by a Decree of a |
| Court of Law; established, a expressed below: | re-established, monumented, re-monum | nented, recovered, found as |
| • | corners, all in the same town and ran | 23 20 21 220 2 |
| on this certificate. | | 12 11 32 33 34 35 3 |
| | | 13 |
| A. Description of original | monument and accessories and/or si | ubsequent restoration: |
| M-12 4 corner for Se | ction 36. | |
| (Spr. Pi | ne 5" N 53° W 19 links). | 's mkd. (Spr. Pine 6" S 67° W 33 links) |
| P. 223. (1 | MCRC survey) Wit's mkd. (N 40° W | % RLS cap by single proportion. Cert. of Sur. Rec. L. 1, 52.2' 12" J. Pine) (N 25° E 62.3' 16" Oak) (S 60° E 36.0' 12" |
| L.C.R.C. I | Rec. L. 1, P. 30. Same wit's. | 52.5 12 0. They (# 25 L 52.5 10 0dk) (5 00 L 50.0 12 |
| Dec. 1976- Donald E. | Marlatt P.S. #18660, Fnd. ½" bar | in mon. box & placed cap on same in a boundary survey of the |
| | | of Sur. Rec. L. 2, Pgs. 328 & 329 & L. 3, Pgs. 85 & 86. |
| No wit's r Sep. 4982. July 1983 | | P.S. #25852, Fnd. ½" Iron in mon. box. Cert. of Sur. Rec. L. 3 |
| Pgs. 173, | 174, 217 & 218. No wit's mkd. | The waster, the garanteen box. Cert. of Sur. Rec. E. 3 |
| June 1995- Fredrick 3 | J. King P.S. #25852, Fnd. ½" bar | & cap #18660 in mon. box. Cert. of Sur. Rec. L. 10004, |
| Pgs. 0267 | & 0268. Wit's mkd: (N 60° W 43.8 | 38' spk. in Fe. Cor. post) (East 33.0' iron & cap #25852 & R.T. |
| | 82.88' spk. in S.W. Sd 10" Oak). | (S 35° W 67.08' spk in S.E. Sd 10" Oak) |
| (1, 2, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, | space to the other on the outer. | |
| B. Description of corner | r evidence found and/or method ap | plied in restoring or reestablishing corner: |
| Fnd. ½" bar & RLS cap | g #18660 in mon. box in the c/l T | ownline Rd. |
| Placed Re-mon cap on | same. | |
| | • | |
| C. Description of monumer | nt for corner and accessories establis | shed to perpetuate locating the position of the corner: |
| M-12 1 corner for Sec | | |
| ½" Bar & Re-mon cap. | Accepted as a careful and far | ithful establishment of the position of the corner. |
| | Group on June 20, 1997. | APPROVED BY OF MIC |
| East 39.97' bar & cap | - | APPROVED BY |
| S 40° E 71.98′ 8″ 0a S 45° W 67.12′ 8″ 0a | | PEER GROUP |
| N 25° W 82.93' 10" Oa | | JUN 2 0 97 LOB. BEAUREGARD & |
| | | VOII A V V グヘン・ をしま CHOMEVAD 「版 |

Jany Beautyard Date 10/17/47
an License No. 18654 Surveyor's Michigan License No. <u>18654</u> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

Placed 60d penny spike, P.S. tag #18654 & blaze. (typ)

POFESSION