MAY 1 6 1997

Montmorency County Remonumentation 00012 Fase 0231

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich DA 107

For corners in	rang nequin	ement of Act 74, Mich. P	-A. 1970
MONTMORENCY (County)	Located In: ALBERT TWP.	Corner Code ##	STATE OF MICHIGAN MONTMORENCY COUNTY Recorded & Filed
Public Land Survey	T _29N_R _2E T R	D-13	11-06-1996 11:07:09
2. Property Controlling	T R T R S T R		A. PANGAN-MCELROY REGISTER OF DEEDS
in Section 3. Miscellaneous Property in Sec.	S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot No,	Recorded Plat		A B C D E F G H I J K L

I, FREDERICK J. KING, in a field survey on _May_30_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10 11 12
- A. Description of original monument and accessories and/or subsequent restoration:
 - D-13 SOUTH 1/4 CORNER OF SECTION 32

Dec. 1839 - Original Post set by Clason, Dep. Sur. - N50°E - 16 1ks (10.56') - 8" Spr Pii N52°W - 27 1ks (17.82') - 8" Spr Pii

Dec. 1970 - Act 74 (Not Rec) by K. Ostling #10068 N50°W - 26.8' - 8" J. Pine $N30^{\circ}E - 4.1' - 7"$ J. Pine Set DNR Pipe & Cap by Prop. Meas.

Cor D-1 (28-1) is 9.4' E

Dec. 1970 - Act 74 (L2, P322) by K. Ostling - Set DNR Pipe & Cap by Prop Meas.

Corner D-13 (29-2) is 9.4' W Cor D-1 T28N-R2E

No Act 132 Found Recorded for this Corner

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - D-13 SOUTH 1/4 CORNER OF SECTION 32 (±14' N of C.L. of E-W trail)

Found J. Wilcox I&C (#14102) - DNR Pipe & Cap GONE
N50°W - 26.8' - Fnd Blz in Rec J. Pine (Not Rec) K. Ostling
N30°E - 4.1' - Fnd Blz in Rec J. Pine - Stump Only (Not Rec)
N10°E - 5.8' - Fnd Spk - No tag - in 8" J. Pine
S40°W - 39.0' - Fnd Spk - No tag - in 8" J. Pine
Corner D-1 - West - 9.4' - Fnd Rec DNR Pipe & Cap, LAYING ON GROUND - Appears to have bee T28N-R2E

hit by bulldozer during recent pipeline construction.

No Original Government Corner Evidence Found

This Corner approved by County Peer Review on June 7, 1996, as the best available evidence of the Re-Establishment of the Original Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-13 - SOUTH 1/4 CORNER OF SECTION 32

Set Mont. Co. Re-Mon Cap & 4" Conc Mon @ Fnd I&C Position

 $\rm N10^{O}E$ - 5.83' - Set S&T above found Spk - E side of 8" J. Pine $\rm S80^{O}E$ - 24.38' - Set S&T S side of 5" Poplar

 $S40^{O}W$ - 38.95' - Set S&T above found Spk NW side of 8" J. Pine $N50^{O}W$ - 26.82' - Set S&T NE side of 12" J. Pine

Corner is ±14' N of C.L. of E-W trail

East - 9.4' - Corner D-1 (28-2) GONE



Surveyor's Michigan License No. 25852

Date October 25, 1996

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1973