SURVEY & REMONUMENTATION

APR 2 4 1995

Montmorency County Remonumentation

LAND CORNER RECORDATION CERTIFICATE iber COLON Sage CONTINUE

	COMMISSION
For	ດດເກືອເຮັ ມາ

Filing Requirement of Act 74, Mich. P.A. 1970

For confers in		` .	, 10 mm 1	A119 A 4	
MONTMORENCY (County)	Located In:	Corner Code ## .	5TATE OF MIC MONTMORENCY Recorded & F	COUNTY	
Public Land Survey	T 29N R 4E T R T R	APPROVED BY	10-19-1994		
2. Property Controlling	T R PEER GROUP A. PAI S T R REGIS			CELROY DEEDS	
in Section	S T R	001			
Miscellaneous Property in Sec.	S T R S T R	/ A #A	Register of Deeds Stamp & File Number		
4. Lot No , Re	ecorded Plat		A B C	DEFGHIJK	
5. Private Claims					
0		•	3		
			4	8 9 10 11	
I FREDERICK J. KING	in a field survey on Augi	ist 2 , 19 94	5		
do hereby certify that under req	uirements of P.A. 74, Michiga	n P.A. of 1970, the corner points men	ntioned 6	17161514	
		ns and rules therefore as required Department of the Interior, Bureau o			
		corner points mentioned in lines 3, 4		20 - 21 - 22 - 23	
above were in conformance with	h the rules of the Michigan B	oard of Land Surveyors or by a Decr	ree of a		
	a-established, monumented	, re-monumented, recovered, for	und as	79 78 77 16	
expressed below:			ا ا ا	29-1-28-1-27-26-1	
on this certificate.	orners, all in the same to	wn and range, may be recorded	12 3		
on this certificate.			13	32 33 34 35	
A. Description of original r	nonument and accessorie	s and/or subsequent restoration		tain july	
M-13 SOUTHEAST CORNER SE		·		prPine - 9.90' (15 lks	
Nov. 1839 - Origina	1 Post set by Lewis Cla	awson, D.S.		r Pine - 21.12' (32 1ks	
States that me	RR Rail was Fnd @ NW Co asurements & evidence	Surveyor - Obtained from L. or of towns 28 & 29 N-R4 & E fnd 2 Mi. S & 1 Mi E - Check yor - Obtained from L.G. Bea	5E & was accepted as a k closely with Govern	a valid Cor States ment records.	
Meas: &	RR Rail at NW Cor of	Sec. 6.	-	to the second	
L.G. Be	auregard, PS #18654 - :	1/2" Iron Bar & RLS Cap set Set by Rec Dist along Co. li nd 4" RR Iron shown by DNR S	ine from N60E - 6"	r Pole - 147.47' Thorn Apple - 48.78' Oak - 41.60'	
B. Descholion 37 comer 8	ecorped regrathy 8 year	hod applied in restoring or ree	stablishing corner:		
M-13 SOUTHEAST CORNER S	ECTION 36				
8-2-94 - Fnd Rec Be	auregard I & C	S.50°E - 147.47' - Fnd Spk	in P Pole		
	-	N.600E 48.7' - Fnd Blz	in Thorn Apple		
		N.700W 41.5' - Fnd Blz	in Oak		
		No 1839 Wit Fnd	in water		
	•	• •		·	

This Corner Approved by County Peer Review on October 10, 1994, as aneadeful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-13 SOUTHEAST CORNER SECTION 36

8-2-94 - Placed Co. Re-Mon Cap on Fnd 1/2" Iron Corner is ± 3' W of N-S Fnc to N & ± 24' E of N-S Fnc to W & is in C.L. Rd to E (Valley Rd) & C.L. Rd to S (Flynn Rd) NO50E - 27.8' - Set Treated 2"x4" 0 Fnc Cor. N60°E - 49.02' - Set Tag on S side 8" Thorn Apple

 550° F - 147.39' (R-147.47') Set Tag above Spk Fnd on NE side Pwr Pole

S309MM2 40.37' - 6th Steel Post S of N end Chain Link Fnc.

N70°W - 41.56' (R-41.60') - Set Tag N side of Middle Oak in Tri Oak Clump.

FREDERICK J. KING PROFESSIONAL SURVEYOR No. 25852 OFE SSION

Surveyor's Michigan License No. 25852

FORM APPROVED BY MICHIGAN STATE BOARD OF DARK REVISED REVISED JAN