Montmorency County Remonumentation

Liber <u>12</u>	_Pago <u><i>55</i></u>
-----------------	------------------------

Lot No.

expressed below:

5. Private Claims

LAND CORNER RECORDATION CERTIFICATE


For corners in		Filing Requi	Filing Requirement of Act 74, Mich. P.A. 1970		
	Montmorency (County)	Located In:	Corner Code ##	S os	
1.	Public Land Survey	T <u>30N</u> R <u>2E</u> T R T R	(A-5)	ELROY SU	
2.	Property Controlling in Section	S T R S T R			
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Numb	



		•
ı, Larry G. Beauregardin a field survey on	October	, 19 _93,
do hereby certify that under requirements of P.A. 74, Mich		
in lines 1 and 2 above were in conformance with regu	lations and rules there	efore as required in the
current manual of survey instructions of the United Stat	tes Department of the	Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that	the comer points men	tioned in lines 3, 4 and 5
above were in conformance with the rules of the Michiga	an Board of Land Surve	evors or by a Decree of a

Court of Law, established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

(A-5)GLO Post set by Lewis Clason April 1840. Wits: Hard Maple 12" S 12° W 28 links

__ , Recorded Plat .

Beech 6" N 56° W 19 links Gordon E. Slattery P.E. #3694 Project Engineer MDOT in 1967 set 1" Re-bar flush with

bit surface. Wits marked: (S 45° W 58.98' 21" Maple) (S 30° W 91.82' 7" Maple) (S 78° W 75.79' 6" Ironwood).

Donald E. Marlatt P.S. #18660 fnd. 1" Re-bar & wits by Slattery in 1978 & in 1985 marked wits: (S 30° W 91.82 9" Maple East 33' \(\frac{1}{2} \)" rod.)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fnd. 1" Re-bar 2" below pavement 2'± West of M-32 C/L. (Re-placed 1" bar with $\frac{1}{2}$ " bar & 3" dia. Aluminum cap marked Montmorency Co. Re-Mon. Corner (A-5)& set Mon. box.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A-5)Sec. Cor. Comm. to Sec's 12 & 13, T30N, R1E & Sec's 7 & 18, T30N, R2E

>" bar & Re-Mon. cap #18654 in Mon. box. Accepted as the best available evidence of the position of the original corner, approved by the Peer Group on September 24, 1993.

½" bar & cap #18660 33.01 s 70° W 110.9' P. Pole

N 65° W 85.121 s 55° W 88.301 Tw. 9" Beech

	0	0 1		17 77 92	
Signed by	hanu	Strangard	Date	16-61-13	
		10(5)			

TO BE THE CONTRACTOR OF THE PROPERTY OF THE PR

Surveyor's Michigan License No. ___18654 REVISED MAY 14, 1975 REVISED JAN., 1983