LAND CORNER RECORDATION CERTIFICATE

	ruing Requirement of	Act 74, Mich. PA 1970	
For Corners In: Montmorency (County)	Located In Corner C	ode#	
Public Land Survey Property Controlling	T 30N R 3E D-11 T 30N R 3E D-13		
in Section 3. Miscellaneous	S T R		¥2
Property in Section	S T R	Register of Deeds Star	mp & File Number
4. Lot No:	Recorded Plat:	A B C D E F G H	1 J K L M
5. Private Claims:		2 6 5 4 3	2 1
I, <u>Carl T, Kiiskila</u> , in a field survey on <u>March 8, 2011</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:		at under In lines 1 quired in Int of the Ithat the Ithe rules Ithat the Itha	14 13 24
NOTE: Not more than be recorded on this ce	2 corners, all in the same town and range, rtificate.	may 10 30 29 28 27	25
		12 31 32 33 34	35 36
A. Description of original monument and accessories and/or subsequent restoration:			
<u>D-11</u> – ¼ corner comm. to sections 29 & 32, T30N,R03E <u>D-13</u> – S ¼ corner section 32, T30N,R03E			
P.S.# 50438 – Re	Oak " Twin Maple	1995 – Remon L.C.R.C. – L.12, p.179 – D P.S.# 18660 – Found D. Porter's ½ with concrete monument and remon S45°E 40.28' 13" Balsam S02°W 15.7' 7" Balsam N67°W 13.9' 8" Balsam N85°E 17.7' 11" Poplar	" rod and cap. Replaced
B. Description of corner	evidence found and/or method applies in rest	oring or re-establishing corner:	
<u>D-11</u> – ¼ corner comm.	to sections 29 & 32, T30N,R03E	<u>D-13</u> – S 1/4 corner section 32, T30N,R038	=
L.C.R.C. – L.13, p best available evid	nonument with Montmorency remon cap per 0.193. Accepted found monument as the dence for the position of the original corner. vidence to dispute the location for the	Found concrete monument with Mor L.C.R.C. – L.12, p.179. Accepted to best available evidence for the posit Found no other evidence to dispute corner.	ound monument as the ion of the original corner
	nent for corner and accessories established to		
	to sections 29 & 32, T30N,R03E	<u>D-13</u> – S ¼ corner section 32, T30N,R03	
4"dia. x 36" long conc. mon. w/ 3"dia. alum. Mont. Co. cap 4"dia. x 36" long conc. mon. w/ 3"dia. alum. Mont. Co. cap			
*S55°E 29.61' to fd. S01°W 27.51' to set *S74°W 2.82' to fd. I *N40°W 48.20' to fd.	N&T#50438 on N side 22" R. Oak N&T#50438 on E side 10" Tw. Maple Stump t N&T on E side 13" R. Oak N&T#50438 on S side 19" R. Oak N&T#50438 on NE side 17" Tw. R. Oak	Witnesses: N55°E 16.08' to set N&T on SE side 6" *N70°E 17.70' to fd. N&T#18660 on N s East 8.27' to fd. Mont. Co. mon. (C.C. *S50°E 40.30' to fd. N&T#18660 on SW S12°W 32.35' to set N&T on W side 5" *N73°W 13.85' to fd. N&T#18660 on NE	ide 11″ dead Poplar N ¼ sec. 5, T29N,R03E) ′ side 14″ Balsam FIr R. Oak
* Witness of previous	record.	Set Blue Carsonite Post 1' North	TATE OF MICHIGA

LAND SURVEYOR 33981
FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN.
REVISED J. REVISED J.

* Witness of previous record.

Surveyor's Michigan License No.:

33981

CARL KIISKILA

SURVEYOR