Montmorency County Remonumentation

APR 2 4 1995

4. Lot No.

expressed below:

5. Private Claims __

LAND CORNER RECORDATION CERTIFICATE

A. 1970

For corners in	COMMISSION	Filing Requirement of Act 74, Mich	1. P.,
Montmon			1

Located In: Avery Twp. Corner Code ## 1. Public Land Survey T __30NR __3E APPROVED BY _ R __ R __ PEER GROUP 2. Property Controlling __ R _ in Section __ T ___ R _ AUG 0 5 3. Miscellaneous __ T ____ R __ Property in Sec.

STATE OF MICHIGAN MONTMORENCY COUNTY Recorded & Filed,

11-02-1994 15:43:03

A. PANGAN-MCELROY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Larry G. Beauregardin a field survey on _ _ May .: 19 <u>-94</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines $3,4\,\mathrm{and}\,5$ above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO post set by Lewis Clason April, 1840. Wits: Tamarack 12" S 70° W 12 links (M-5)

____ , Recorded Plat _

Cedar 7" N 50° W 11 links

Frank N. Smith P.S. #754 in 1948 set 3" square Cedar stake. Wits: (6" Birch S 70° E 10.0').

Larry G. Beauregard P.S. #18654 in 1973 found 4" x 4" square stake below the surface of the ground. This corner was set by Frank Smith. Replaced with a concrete monument and P.S. cap #18654. Wits: (4" Cedar 5 20° W 17.61') (10" Balsem S 33° E 18.57') (10" Cedar N 45° E 18.64') (6" Birch S 70° E 10.00' (R).

Donald E. Marlatt P.S. #18660 in 1974 found a concrete monument set by Larry Beauregard in 1973. Wits: (4" Cedar S 20° W 17.61') (10" Balsam S 33° E 18.57') (10" Cedar N 45° E 18.64')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M-5)Found concrete monument & witnesses from previous survey by myself in 1973, W.O. #60-271. Placed 3" Aluminum cap #18654 marked Montmorency County Remonumentation corner.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M-5)Section corner common to Sections 12, 13 and 7, 18, T 30 N, R 3 E and T 30 N, R 4 E

> Conc. mon. and 3" Alum. cap #18654. Accepted as a careful and faithful establishment of the position of the corner. Approved by the Peer Group on August 5, 1994.

6" Cedar S 20° W 17.61' (R) 11" Cedar N 45° E 18.64' (R) MOOT wits. 10" Spruce S 33° E 18.57' (R) 6" Birch stump N 20° W 10.00' (old) F. Smith

94

Placed 20 penny spike & P.S. tag #18654 (typ)

Signed by	Bear	uneard	Date	11/2/
Suprevor's Michigan License No.	18654			

M APPROVED BY MICHIGAN STATE BOARD OF LAND QURVEYORS, JAM. 28, 1976

REVISES JAN., 1903