SURVEY & REMONUMENTATION

APR 2 4 1995

Montmorency County Remonumentation iber 00012 Page 0101

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION For corners in

4. Lot No.

Private Claims _

	Montmorency (County)	Located In: Avery Twp. Corner Code ##
1.	Public Land Survey	Т <u>ЗО</u> N R <u>ЗЕ</u> (M-7)
	·	T R APPROVED BY
2.	Property Controlling in Section	STR STR
3.	Miscellaneous Property in Sec.	S T R

STATE OF MICHIGAN MONTMORENCY COUNTY Recorded & Filed

11-02-1994 15:43:28

A. PANGAN-MCELROY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

Larry G. Beauregardin a field survey on	Mey	19 94
do hereby certify that under requirements of P.A. 74, Michiga		
in lines 1 and 2 above were in conformance with regulation	ins and rules therefo	re as required in the
current manual of survey instructions of the United States (Department of the Inte	erior, Bureau of Land
Management or by a decree of a Court of Law and/or that the	corner points mention	ned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan B	oard of Land Surveyo	rs or by a Decree of a
Court of Law; established, re-established, monumented expressed below:	, re-monumented, r	ecovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO post set by Lewis Clason April 1840. Wits: Hemlock 12" S 39° W 42 links

__ , Recorded Plat _

Hemlock 12" N 64° W 41 links

10

Frank N. Smith P.S. #754 in 1924 set square cedar post. Wits: (12" Birch S 85° W 31.9') (6" Birch N 20° W 30.5!).

Donald E. Marlatt P.S. #18660 in 1974 set 11 rod along side of square cedar. Recorded L. 1, P. 572 in Montmorency County Records. LCRC filed, L. 1, P. 107. Wits: (4" Maple N 85° E 35') (3" Maple S 15° E 7.9'). (New wits Donald E. Marlatt P.S. #18660 in 1982 found square cedar post & ‡" rod. Wits: (4" Maple N 85° E 35') (3" Maple S 15° E 7.91).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found square cedar post by F. Smith & $\frac{1}{2}$ " bar & RLS cap by D.E. Marlatt. Also found record witnesses. (M-7)Replaced cedar stake and 2" bar and cap with a 4" x 36" concrete monument and a 3" Aluminum cap #18654 marked Montmorency County Remonumentation corner. This monument was set on the East side of fence post with a fence line running North.

Description of monument for corner and accessories established to perpetuate locating the position of the corner Section corner common to Sections 13, 24, 18 and 19, T 30 N, R 3 E and T 30 N, R 4 E Concrete monument and Re-mon. cap #18654. Accepted as a careful and faithful establishment of the position of × 36"

the corner. Approved by the Peer Group on August 5, 1994.

12" Birch N 10° W 29.5' (R) – Face F.N.S. 5" Spruce S 75° W 11.73' 8" Maple N 85° E 35.0' (R) D.E.M.

9" Maple S 10° E 7.9' (R) D.E.M. 6" W. Pine N 50° W 9.101

Date

Placed blaze, 20 penny spike & P.S. tag #18654 (typ)

Signed by fany	Bear	meand	
Signed by			
Surveyor's Michigan License No.	18654		_

11	1	7	/	0	1	
	L	4		7_	Y	