## SURVEY & REMONUMENTATION

APR 2 4 1995

## Montmorency County Remonumentation Liber 00012 Page 0103

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION For corners in		Filing Requirement of Act 74, Mich. F		
	Montmorency (County)		Located In: Avery	Twp.Corner Code ##
1.	Public Land Survey		' ''	APPROVED BY PEER GROUP
2.	Property Controlling in Section	s s	T R _ T R	AIVO O 5 OA
3.	Miscellaneous Property in Sec.	s		B.

STATE OF MICHIGAN MONTMORENCY COUNTY Recorded & Filed

11-02-1994 15:43:52

A. PANGAN-MCELROY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

Larry G. Beauregardin a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

A. Description of original monument and accessories and/or subsequent restoration:

GLO post set by Lewis Clason April 19, 1840. Wits: Aspen 6" S 40° W 15 links (M-9)

\_\_\_\_\_ , Recorded Plat .

Private Claims \_\_\_

expressed below:

Aspen 5" N 14° W 18 links

Frank N. Smith P.S. #754 in 1924 set cedar post and one witness. Montmorency County Surveyor. Wits: (Y. Pine stump N 28° E 37.0').

Donald E. Marlatt P.S. #18660 in 1976 found square cedar stake & 1" pipe. Wits: (8" Balsam N 80° W 26.6') (8" Balsam N 65° E 42.3') (Also 1" pipe 69.9' West, unknown origin).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" x 3' pipe of record in line with H. wire fence N, S & E,  $12^{n\pm}$  above ground. Re-placed with  $4" \times 36"$  concrete munument and a 3" Aluminum cap #18654 marked Montmorency County Remonumentation corner.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Section corner common to Sections 24, 25, 19 and 30, T 30 N, R 3 E and T 30 N, R 4 E (M-9)

 $4^{\circ}$  x 36° concrete monument and Re-mon. cap #18654. Accepted as a careful and faithful establishment of the position of the corner. Approved by the Peer Group on August 5, 1994.

11" Soruce N 68° W 26.79' (R) 5" Spruce S 80° W 25.53% (New) 11" Balsam N 60° E 42.55' (R) 6" Balsam S 5° E 26.15" (new)

Placed blaze, 20 penny spike & P.S. tag #18654 (typ)

Pany & Beauregard Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 19 BEYISED JAN., 19