

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. _____ N. S., R. _____ E. W.		
2. PROPERTY CONTROLLING IN SECTION <u>7</u> , T. <u>30</u> N. R. <u>4</u> E.	●      ●	<u>13; 14</u>
3. MISCELLANEOUS PROPERTY IN SECTION <u>7</u> , T. <u>30</u> N. R. <u>4</u> E. XX = 305.2 N and 495.0 W of 14.	●      ●	<u>9/C-4; XX</u>
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

Montmorency

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on April 25, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:


**A. Description of original monument and accessories and/or subsequent restoration:**

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

- 13 Set by standard survey procedure.
- 14 Set by standard survey procedure.
- 9/C-4 Set to delineate property boundary.
- XX Property corner on road right-of-way.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

	13	14		9/C-4
Set 3' of 1" pipe	Set 2½' of 1" pipe	Set 3' of 1" pipe		Set 3' of 1" pipe
7" Spruce N18°E 26.0'	PK nail in NE side of	12" Cedar N80°E 14.9'		8" Maple S40°W 20.0'
11" Spruce N89°E 59.6'	16" R. Pine N66°W 53.1'			
	PK nail in NW side of			
	8" Maple S45°W 50.15'			
Set 3' of 1" pipe				
8" W. Birch S84°W 56.8'				
7" Maple N05°E 80.8'				
€ of M-32 South 35'				



SIGNED BY Kenneth Ostling DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. Montmorency