STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		COUNTY	
		T <u>31</u>	R 1 E
DESCRIPTION OF CORNER	S 1/16 corner on N-	S 1/4 line	- -
CORNER MONUMENT	Set 2' of 1" pipe		
DATE MONUMENT PLACED AND	WITNESSED	9-11-72	
WITNESSES TO CORNER	•		
N		S 53 W	11.1'
29	5" Maple	S 39 E	27.8'
•	AND		
CIRCLE CORNER REGISTER	PRD	·	
ESCRIPTION IN DETAIL AS	TO HOW CORNER WAS LOCA		RESTORED.
ESCRIPTION IN DETAIL AS	TO HOW CORNER WAS LOCA		RESTORED.
Set by standard survey p	TO HOW CORNER WAS LOCA		RESTORED.
Set by standard survey p KENNETH J. OSTING LAN SURVEYOR NO.	TO HOW CORNER WAS LOCA		RESTORED.
Set by standard survey portion in DETAIL AS Set by standard survey portions KENNETH J. OSTLING LAND SURVEYOR	TO HOW CORNER WAS LOCA		RESTORED.
Set by standard survey por Michael Survey or No. 10038 SURVEYOR S SEAL	TO HOW CORNER WAS LOCA	vision of sections. Calculation DATE	9-13-72