

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 31 N. R. 3 E.	G-10; H-10; I-10
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. S., R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S., R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on July 24, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:


- G-10 Found 1/2" rerod GFD's northeast NBT in place. Old fence in line east.
- H-10 Set at computed true intersection of 1/4 lines.
- I-10 Set midpoint on line between section corners. Could not recover GFD corner, but this point nearly agrees with GFD witness.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-10	H-10	I-10
DNR monument	2 1/2' of 1 1/4" pipe & red-top post	DNR monument & red-top post
13" W. Pine N26°W 60.8	6" Cedar N05°W 22.7	*7" Cedar N35°W 7.5
*17" B. Oak N70°E 37.8	9" Cedar N83°W 31.8	6" Cedar N24°E 22.7
*GFD witness		Corner fence post S62°W 7.3

SIGNED BY Kenneth J. Ostling DATE 11/24/74

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ MONTMORENCY COUNTY