DEC 1 8 1995

Montmorency County Remonumentation iber 00001 Page 0531

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 iber 00012 Page 0154

For corners in	-	•							
Montmorency (County)	Located In: Corner Code ##			STATE OF MICHIGAN MONTMORENCY COUNTY					
Public Land Survey		K-13	Recor	ded & F	iled	-			
3. Miscellaneous	T R R T R R R R R R R R R R R R R R R R	PHOVED BY EER GROUP	09-22-1995 11:31:35 A. PANGAN-MCELROY REGISTER UF DEEDS Register of Deeds Stamp & File Number						
4. Lot No, Rec 5. Private Claims		JB.	2 3	B C 0) E F	G H	J	K L	
Larry G. Beauregard in a field survey on June 5, 19 95				-	e	10-	口	12	<u>} </u>
do hereby certify that under requir in lines 1 and 2 above were in co- current manual of survey instructi Management or by a decree of a Co- above were in conformance with the Court of Law; established, re-e- expressed below:	onformance with regulations an ions of the United States Depar ourt of Law and/or that the corne he rules of the Michigan Board o	id rules therefore as required then tof the Interior, Bureau of points mentioned in lines 3, 4 of Land Surveyors or by a Decre	in the Land 7 and 5 å	19 20	21-	22-	23-	24	J 4 5
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.				-31 - 32	33	34	35	36	 }
A. Description of original mod 4-18-1840, Lewis Clason, De 6" H. Maple) (N 84° E 54	puty Surveyor, Set post o			marked:	(N 73°	° W 31	ß lin	iks	

1968, Norman C. Caldwell, R.S. #12018, Set ½" bar & RLS cap #12018 for standard corner Sections 35 and 36, T 31 N, R 4 E, no data available.

2-21-1985, Clifford C. Lindgren, P.S. #14098, MDOT, Found a RLS cap #12018 on a standard rod, buried 5", 26.5' West of centerline of M-32. No old witnesses. Witnesses marked: (\$ 55° E 68.40' Power Pole) (\$ 25° W 37.05' Guy Pole) (S60° W 45.14' 16" Thornapple clump) (N 40° W 29.60' 3" Thornapple) (N88°-49'-34.80" E 22.14444' 5/8" steel pin ir monument box - N. & corner of Sec. 1, T 30 N, R 4 E). Filed LCRC, Rec. L. 1, P. 382, Montmorency Co. Records.

1986, Jim Schwandt, P.S. #26466, Granger Engineering, Inc. Found RLS cap #12018 on rod buried 5" and witnesses recorded: (S 55° E 68.40' Power Pole) (S 25° W 37.05' Guy Pole) (S 60° W 45.14' 16" Thornapple, clump) (N.40° W 29.60' 3" Thornapple).

3-10-1988, Larry G. Beauregard, P.S. #18654, R.S. Scott Associates, Inc. Found existing ½" bar & RLS cap #12018 of Record 22.14' West of 5/8" pin in monument box and witnesses recorded: (S 55° E 68.40' Power Pole) (S 25° W 37.05' Guy Pole) (S 60° W 45.14' 16" Thornapple in clump). Certificate of Survey Rec. L. 3, P. 432, Montmorency Co. Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" x 19" bar without I.D. cap set by MDOT survey crew. This bar replaced the ½" bar & cap mentioned above due to the reconstruction of Highway M-32.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Southwest corner of Section 36, T 31 N, R 4 E

Placed 4" diam., x 36" concrete monument and Montmorency County Remonumentation Cap P.S. #18654. Accepted as the best available evidence of the position of the original corner. Approved by the Peer Group on June 2, 1995.

22.06' 5/8" bar in monument box, N. 1 corner Section 1, T. 30 N, R 4 E.

N 60° W 56.75' Placed P.K. nail & P.S. tag #18654 in top of steel corner fence post.

S 80° W 125.93' 8" Elm Placed blaze, 60d penny spike & P.S. tag #18654

S 60° W 60.96' Telephone Pole Placed P.K. nail & P.S. tag #18654

S 62° E 108.25' Power Pole Placed P.K. nail & P.S. tag #18654

Signed by Jany Deautegard
Surveyor's Michigan License No. 18654

HSED MAY 14, 1975

E OF MICE

REVISED JAN., 1983