

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 32. NR. 2. E. . .

Montmorency COUNTY

DESCRIPTION OF CORNER Corner common to Sections 13, 14, 23, 24 . . . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . . .

WITNESSES TO CORNER . . . .

8" B. Oak - S17W - 60½ links

7" B. Oak - N66E - 64½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner was found by Forestry Division survey crew  
while making a survey of Section 13. Found axel shaft at corner  
set from probable OBT sites. Good corner ½ mile east.

Corner was placed and witnessed Nov. 5, 1956.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR

DATE 11/19/56