

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 32. NR. 2 E.

Montmorency COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 13 & 24

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

6" B. Oak - N42E - 42 links

6" B. Oak - S1E - 55 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey of Section 13. A very good original corner with both BT stumps in place and a very fine face on the NE BT. Corner had been previously established with a 1 1/2" pipe in concrete.

Corner was placed and witnessed October 1, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buchler DATE 11/19/56  
REGISTERED LAND SURVEYOR