

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T..32. NR..3 E..

-----Montmorency----- COUNTY

DESCRIPTION OF CORNER .. 1/4 Corner common to Sections 18 and 19

DESCRIPTION OF CORNER MONUMENT .. 1" pipe with a 4" brass cap

WITNESSES TO CORNER ... 8" Balsam .. S 44 E .. 36 1/2 links .

.. 5" Balsam .. N 52 W .. 5 1/4 links .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was established by proportionate measurement between section corners by Forestry Division survey crew while making a survey in this area. Could not identify government Cedar BTs, although there are many in vicinity which do not conform to government record.

Corner was placed and witnessed November 13, 1958.

SURVEYORS SEAL

SIGNED *Kenneth J. Ostling* .. DATE .. 11/19/58
REGISTERED LAND SURVEYOR