## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_32. NR\_\_\_2E\_ T 32 NR 3E

Montmorency COUNT
DESCRIPTION OF CORNERSection_Corner_common_to_Sections_13-24-18-19_
DESCRIPTION OF CORNER MONUMENT1"_pipe with a 4" brass_cap
WITNESSES TO CORNER 14" R. Pine S_11 E 189 1/2 links
14 R. Pine West 256 1/2 links.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew while making a survey in this area. Government BTs removed in fire line construction. Set sorner on line over 1/4 and section corner west, which are good government corners, making the east 1/2 mile equal to the west 1/2 mile between 13 and 24. Corner falls in N-S fire line road. This position was considered more in conformity with the calls of the government survey, since a single proportion on the town line between corners 1 mile north and 2 1/2 miles south, which cannot be identified as government corners, would place the corner of 18-19-13-24 about 65 links north of our established position and far beyond the usual inconsistancy of the government survey. This position is further supported by line tree sites in the east 1/2 mile between 13 and 24.

Corner was placed and witnessed November 12, 1958.

SURVEYORS SEAL

SIGNED LEWELL SURVEYOR DATE 11/19/58