MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYOO COUNTY REGISTER OF DEEDS LINDA M. SROWN

**SECTION** 

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MAR 6 PM 12 34

For corners in  Newaygo  (County)	Located in:	Corner Code #	Lineam	. Brown
1. Public Land Survey	T <u>11N</u> R <u>12W</u> T <u>12N</u> R <u>12W</u> T R T R	L-1 V L-13	vol. <b>2</b>	69
2. Property Controlling in Section	STR STR			
Miscellaneous     Property in Sec.	STR STR		Register of Deeds Stamp & File	Number
I, Norman L. Ochs do hereby certify that under a points mentioned in lines 1 at therefore as required in the coperatment of the Interior, B Law and/or that the corner conformance with the rules	, in a field survey on	of 1970, the corner ulations and rules he United States cree of a Court of above were in urveyors or by a	A B C D E F G H I  2 - 6 - 5 - 4 - 3 - 3  4 - 7 - 8 - 9 - 10 - 5  6 - 18 - 17 - 16 - 15 - 7  8 - 19 - 20 - 21 - 22 - 9	14 13 -
Note: Not more than recorded on this	4 corners, all in the same towns certificate.	n and range, may be	11	+++
North One Quarter Corne	common to both sections. r, Section 1, Grant Township, Newa er, Section 36, Brooks Township, Ne		12 31 + 32 + 33 + 34 + 13	35 7 36 7

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Brookfield and Hodgson 1838 7" Maple N25°W 7 Links (4.62')#1 8" Maple N43°E 13 Links (8.58')#2

William M. Jacques (County Surveyor) Book 14 Page 24 April 21, 1904 24" Pine Stump S27°W 51' #3

11.40

Newaygo Engineering and Survey Company 1984 3/4" Pipe 14" Black Oak S20°W 24.8' #4 12" Twin Oak S65°E 57.0' #5 10" Black Oak N15°W 68.22' #6 Ralph A. Smith R.L.S. #3421 Book 70 Page 1 thru 3 June 30, 1959 Set ¾" Pipe half-way between corners 8" Black Oak S20°W 24.8' #4 8" Twin Oak S65°E 57.0' #5 10" Black Oak N15°W 67.7' #6

Robert Wetherell R.L.S. #24624 April 3, 1978 File Number 3010-78 14" Black Oak S20°W 24.8' (old bearing tree) #4 12" Oak S65°E 57.0' (old bearing tree) #5 14" Black Oak N15°W 67.7' (old bearing tree) #6

OVER 🗞

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found %" X 20" Iron pipe in centerline of East and West gravel road and on West edge of pine plantation going North and the condition of the recorded witnesses are: #1 and #2 gone, #3 remains of stump, #4 thru #7 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 3/2" X 20" Iron pipe and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the section corner.

<b>'</b>			DE SE	i.
28" Black Oak S21°W 24.8' Found spike in East side of tree.	. #4	2 P	1 minutes	W.
24"-24" Twin Black Oak S56°E 57.0' Set spike with tag in So	<b>#</b> [/	NORMAN	1	
22" Black Oak N06°W 68.25' Found spike in East side of tre	# ÷!	L. OCHS	1,78	
16"-14" Black Oak N01°E 106.94' Found nail in root in South		LAND	*	
$\alpha A \varphi \alpha \Box$			SURVEYOR	12
Signed by Johnson L. Cohs	Date September 8, 1997	40,0	. 100 . . 22/130 .a	1 - 4
Norman L. Ochs	•	16.1		27 E
Surveyor's Michigan License No. 22439	Form approved by Michigan State Bo	ard of Lan	Surveybeautan 2	971
<u> </u>		•	Reviserbating 2	<b>.</b> 1975
Approved by Peer Review Group on September 9, 1997			Revised Jan	., 1983
Norman t Ochs County Representative				•