MAR 1 9 2000

SECTION

**NEWAYGO COUNTY** 1999 Newaygo County Remonumentation Project REGISTER OF DEEDS

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970 00 FFR 28 PM 1 08

LINDA H. BROWN

For corners in	•		00 150 70	LILT NO
Newaygo (County)	Located in:	Corner Code #	Linda M	1. Brown
Public Land Survey     Property Controlling in Section	T_11N R_11W T_11N R_12W TR TR STR STR	A-13 M-13	'', YOL. 2	278
Miscellaneous     Property in Sec.	STR STR		Register of Deeds Stamp &	File Number
oo nereby certify that under req points mentioned in lines 1 and therefore as required in the cur Department of the Interior, Bure Law and/or that the corner po conformance with the rules of Decree of a Court of Law, estal recovered, found as expressed in	, in a field survey on	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a sted, re-monumented,	5 6 - 18 - 17 - 16 - 1 7 8 - 19 - 20 - 21 - 2 9	3 + 2 + 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
Southwest Corner, Section	31, Ensley Township, Newayg	o County, Michigan.	12 - 31 + 32 + 33 + 3	4 + 35 + 36 -

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. N. Brookfield 1836 10" Beech N40°W 11 Links (7.26')#1 20" Maple N27°E 9 Links (5.94')#2

William M. Jacques (County Surveyor) Book 8, Page 31 1903 ± Measured 80 Chains 11 feet (5291') from the Southwest Corner to the Southeast Corner of Section 36.

Southeast Corner, Section 36, Grant Township, Newaygo County, Michigan.

Patrick A. Salisbury R.L.S. #13594 November 26, 1962 24" Swamp Oak S27°E 18.2' #3 Power Pole N05°E 214.0' #7

Lyle S. Shepherd R.L.S. #503 Witness Book Number 2, Page 155 Pipe 18" White Oak \$291/4°E 18.4" #3 6" Elm S7134°W 77.00' #4

Delos G. Anderson (County Surveyor) Book A, Pages 345 and 346 April 8 thru 12, 1902 Iron Rod 1/2" thick 4 feet long for corner.

Newaygo County Road Commission Sheet 16" Oak N76°E 68.2' #5 30" Elm S53°W 52.4' #6 24" Swamp Oak S27°E 18.2' #3 Power Pole N05°E 214.0' #7

OVER &

LAND SURVEYOR

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 4" Harrison cast iron monument marked "County Surveyor". The centerline of the East and West bituminous road is 2 feet South. The condition of the recorded witnesses are: #1 thru #6 gone, #7 thru #10 good condition, #11 gone, #12 good condition, #13 did not measure, #14 thru #17 good condition.

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 4" Harrison cast iron monument marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Power Pole N08°E 214.55' Set spike with tag #22439 in East side of pole. #7 36" Corrugated Metal Pipe East end N10°E 25.45' to centerline of tube. #8 36" Corrugated Metal Pipe West end N10°W 24.87 to centerline of tube. #9 North One Quarter Corner, Section 1, Tyrone Township, Monument with Kent County brass cap, West 169.50' #10 8" Elm N15°E 26.51' Reset spike with tag #22439 in West side of tree, #12 OF MICHIG Centerline of East and West bituminous road South 2' #14 8" Black Ash N70°W 63.90' Found spike with tag #22439 in Southwesterly side of tree. #15 6" White Oak S50°W 54.65' Found spike with tag #22439 in West side of tree. #16 NORMAN 6" White Oak N70°E 52,75' Found spike with tag L. OCHS

CON 1	oduleasterry side of tree. #17	₫.
Signed by Monay L. Ochs	Date August 16, 1999	4
Norman L. Ochs		_ <u>}</u>
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Le	and S

Approved by Peer Review Group on \_\_August 19, 1999 Norman L. Ochs, County Representative.

## SURVEY & REMONUMENTATION

MAR 1 8 2000

A. Description (cont.)

Patrick A. Salisbury R.L.S. #13594 1972 Found 1¼" Pipe 30" Oak S30°E 19.43' #3 36" Corrugated Metal Pipe East end N10°W 25.5' #8 36" Corrugated Metal Pipe West end N10°W 25.0' #9

SECTION

Norman L. Ochs R.L.S. #22439 1979 Found ½" Rod 36" Corrugated Metal Pipe West end N10°W 25.0' #9

Norman L. Ochs R.L.S. #22439

LCRC #686 September 26, 1985 Found ½" Rod with large stones around it, 2 feet North of the centerline of the East and West road. No witnesses found. The distance to the North One Quarter Corner of Section 1, T10N R12W, Kent County, is Harrison cast iron monument marked "County Surveyor".

5" Elm N50°E 45.21' #11 2" Elm N15°E 26.51' #12

3/8" Pipe in centerline of Juniper Avenue East 332.02' #13
North One Quarter Corner, Section 1, T10N R12W, West 169.50' #10
Centerline of the East and West blacktop road South 2' #14

Norman L. Ochs R.L.S. #22439 April 28, 1988 Drawing Number 88028B 5" Elm N50°E 45.21' #11 2" Elm N15°E 26.51' #12 North One Quarter Corner, Section 1, T10N R12W, West 169.50' #10

James J. Keller R.L.S. #16093

March 2, 1991

Measured 2637.46 feet from the Southeast Corner to the South One Quarter Corner of Section 36 and measured 5273.17 feet from the Southeast Corner to the Southwest Corner of Section 36.

Norman L. Ochs R.L.S. #22439
February 29, 1996 Found 4" diameter Harrison cast iron monument 8" Black Ash N65°W 63.90' #15
4" White Oak S50°W 54.68' #16

5" Elm N60°W 52.72' #17

8" Elm N15°E 27.75' #12

V . . .