1993

REGISTER OF DEEDS MARLENE TOOGOOD

Surveyor's Michigan License No. _

Approved by Peer Review Group Dec. 21, 1993 Norman L. Ochs, County Representative

COMMIS	SECN LAND COL	RNER RECORDATION CERT	TIFICATE PRANTE		
	Filing Red	juirement of Act 74, Mich. F	P.A. 1970 _{04 JBN}	21 PM 3	24
For corners in NEWAYGO	Located In:	Corner Code ##	•		
(County)			Mark	ana 100g	zoed
1. Public Land Survey	T 11N R 13W T R R T R R T R R		vol. C	101 ME 1	03
Property Controllin in Section					
Miscellaneous Property in Sec.	S T R S T R		Register of De	eeds Stamp & F	File Number
4. Lot No	_ , Recorded Plat		A 8	0 5 5 6 0	
5. Private Claims				CDEFG	HIJKLM
			3	-5-4-	3-2-1-1
Norman I Oaha	Do	aomhan 5 03	4 - 7		10
	, in a field survey onDer er requirements of P.A. 74, Michigan		tioned 5		
in lines 1 and 2 above w	ere in conformance with regulation	is and rules therefore as required	in the	1'7 1 '6 	15 14 13
Management or by a decre	instructions of the United States De ee of a Court of Law and/or that the c	orner points mentioned in lines 3, 4	and 5 8 19	2021	22-23-24
	ce with the rules of the Michigan Bo ed, re-established, monumented,				
expressed below:			1030	-29 -28	27-26-25
on this certific	n 4 corners , all in the same tow cate. ion 6, Ashland Twp.	n and range, may be recorded	11 12 31	32 33	343536
G.L.O. J. Mulle 12" Beech N81°W	inal monument and accessories tt 1837 23 1ks (15.18') #1 38 1ks (25.08') #2	s and/or subsequent restoration April 16, 1959 Ralph A. Smith #3421 Field Book 84A Pg. 25 Fd. 1-1/2'' pipe with	n: NCRC Sh P Pole 5 30" Map	eet Iron N88°W 77.7' le Sl3°E 78	
1903 William M. Book A pg. 369 Fnd. good cor. p set by W. S. Mer O.B.T. stumps	ost that was	glass & crockery 8" Elm N75°+E 75.2' # 6" Elm N60° W 57.4' # CL Ditch North 25' #5 CL Ditch West 11' #6	1978 C1 #3 5'' Sass #4 4'' Pop1	inton E. Co . N58°W 29. ar N62°E 23 S37°E 36.64	.35' <i>#</i> 9 3.57 ' <i>#</i> 10
In 1893 W. S. M no witnesses. Se In 1903 Wm. Jacq Merrill' and lef In 1959 R. A. Sm broken crockery In 1993 N.E. & S 1 thru 4 and	her evidence found and/or meth herrill Surveyed Section he book A, Pg. 131 & 13 ques surveyed Sec. 31, ht no witnesses. See B hith, RLS #3421 surveye and glass. See F Book found 1-1/2" pipe, gl 7 and 8 are gone, the he crockery & glass	n 1 of Bridgeton Twp. 2. of Garfield Twp., and ook #1, Pg. 24 & 25 ¶ d Sec. 6, of Ashland T 1, 84A pg. 25. ass & crockery. Condi 5 and 6 fit good,	and set a post found "a good Register of De Twp. He found ition of record and 10 goo	d corner pos eds. a 1-1/2" pi ded witnesse d conditi	st set by W.S ipe with es is on
Accepted 4" Har accepted as a ca 5" Sass N57°W 30 12" W. Oak S37°E 3" R. Pine S40°W 1/2" rod (Burt W 5" Maple S55°E 2	nument for corner and accessor rison cast iron monument reful and faithful ree 1.15' Spike in North sid 1.36.57' Spike in North 1.57.07' Spike in North 1.57.07' Spike in South sid 1.73' Spike in South sid	nt as a substantial mastablishment of the or de of tree #9. side of tree #11. erly side of the tree. 07'. (RLS #17639)	arker for the S riginal corner	NOR NOR L. O	MAN CHS 439
M	La D		D1 - 00 7	993	MD SUR
Signed by / Lanna	an L. Ochs	Date	December 20, 1	993	A MANAGEMENT
Surveyor's Michigan Lie	27/130		CODM ADDROVED BY MICKLES	M STATE ROARD OF LAND	SURVEYORS JAN. 28, 1971

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1985