## SURVEY & REMONUMENTATION

COMMISSION

For corners in

APR 2 4 1995 1994 NEWAYGO COUNTY REMONUMENTATION PROJECT

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

VOL 001 PAGE 79

Neway go	Located'In:	Corner Code ##	NEWAYGO COUNTY REGISTER OF BEEDS
Public Land Survey	T <u>11N</u> R <u>13 W</u> T R	<u>C-3</u>	MARLENE TOOGOOD
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R  T R  S T R  S T R  S T R  S T R		'95 MAR 14 PM 3 52  Marlana Toogood  Register of Deeds Stamp & File Number
	Recorded Plat		A B C D E F G H I J K L N
Norman L. Ochs do hereby certify that under re in lines 1 and 2 above were i current manual of survey instr Management or by a decree of above were in conformance wi Court of Law: established, expressed below:  NOTE: Not more than 4 con this certificate. W Corner, Section A Description of original ELO James H. Mull O'' Beech S53°E 8 2'' Hemlock N65°W  B. Description of corner end on September 16, set 4'' Harrison of From the SW cor.	guirements of P.A. 74, Michigan P.A. or n conformance with regulations and ructions of the United States Departm a Court of Law and/or that the corner in the rules of the Michigan Board of re-established, monumented, re-motores, all in the same town and corners, all in the same town and corners and corners.	dier 16, 19 94  1970, the corner points ment rules therefore as required then to the Interior. Bureau of points mentioned in lines 3, 4.  Land Surveyors or by a Decreonumented, recovered, four range, may be recorded.  I range, may be recorded.  Newaygo County or subsequent restoration 4-16-59 R.  Find. end wood stak 1-1/2" x 7" clmp.  P.Pole N5  Cor. Fe P.  Book 4A,  Measured to the S-  polied in restoring or reest.  Ochs, found 3/4 on the exact loc f.  Section 5.	in the fland and 5 and as a second and as a se
Condition of reco #6 gone, #7 good	orded witnesses is: condition, #8 gone,	#1 thru #3 gone #9 good condit	, #4 good condition, #5 and ion.
			action the position of the corner
et a 4" Harri ind is accepted a 1/2" rod & cap So	son cast iron mon. is a careful and fai outh 32.95' #9 35.89' Spk on N sid 8' Blass cap & nail	as a substantia thful reestabli	NORMAN L. OCHS LAND SURVEYOR 22439
Signed by Norman L.	Ochs 22439		ovember 3, 1994
	e No. 22439 Review Group on Nove		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN 1983

## A cont.

2691.28 ft. from the SE cor. to the E-1/4 cor. of Sec. 6.

5-18-59 Blass-Griffin-Paquette Found Flat iron bar 2" x 4" P.Pole N56°W 58.82' Spike in Pole. #4 Fe Corner South 2639' #5 Elm Clump S88°E 63.69' #3

George Blass RLS # 5489 Measured 2644.89 ft, from the NW cor, to the W-1/4 cor. of Sec. 8. Measured 2639.00 ft. from the SE cor, to the E. meander cor, on the S line of Sec. 6.

1974 Clinton E. Cole RLS #17615
Found corner.
P.Pole N62°W 63.34'#4
6" Poplar S69°E 69.80" #6
Buried phone cable riser N48°E 42.65".
Measured 2646.79 ft. from the NE cor. the N-1/4
cor. of Sec. 7.
Recorded in the plat of "Riverhills."

12-16-76 Newaygo Eng. & Survey Co.
Found 3/4 Pipe - 1 ft. underground w/1/2" rod.
Tele. Riser N52°E 47.50° (center) #7
P.Pole N54°W 57.83° Spike on face #4
4" Basswood S41°E 57.61° Spk. on NE side of tree. #8.
Measured 2674.48 ft. from the SW cor. to the S-1/4 cor. of Section 5.
Measured 2691.92 ft. from the SW cor. to the W-1/4 cor. of Sec. 5.
Measured 2632.47 ft. from the SE cor. to the E. meander cor. on South Section line of Sec. 6.

5-10-79 James G, Campbell RLS #15397 LCRC #492 Found 3/4" Pipe
Tel. Riser N52°E 47,50° #7
P.Pole N54°W 57.33' #4
-4" Basswood S41°E 57,61° #8

See survey recorded in Series J, No. 8081.

8-24-87 Newaygo Eng. & Survey Co. Found 3/4" Pipe 1/2" rod and cap South 33.00 #9