

1996 Newaygo County Remonumentation Project

**NEWAYGO COUNTY** REGISTER OF DEEDS LINDA M. BROWN

MAY 2 8 1997

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

COMMissi	FILING REQUIR	EMENT OF ACT /4, MICH. P.	.A. 1970 J	L LED TS	
For corners in Newaygo (County)	Located in:	Corner Code #	Ċ	Linda V	n. Brown
Public Land Survey	T <u>11N</u> R <u>13W</u> T R T R T R	<u>C-11</u>	vol. <b>1</b>	PAGE	221
Property Controlling     in Section     Miscellaneous     Property in Sec.	STR STR STR STR	Reg	ister of Deeds S		• •
4. Lot No, Records 5. Private Claims	ed Plat		7 - 0 - 5	E F 9 11	
i, Norman L. Ochs do hereby certify that under require	ments of P. A. 74, Michigan P.A	A. of 1970, the corner	3 4 5		
points mentioned in lines 1 and 2 al therefore as required in the current Department of the Interior, Bureau Law and/or that the corner points	manual of survey instructions of Land Management or by a	of the United States decree of a Court of	7		14 3-
conformance with the rules of the Decree of a Court of Law; establish recovered, found as expressed below.	ned, re-established, monument		9	- - - -	
Note: Not more than 4 co recorded on this ce		own and range, may be	11 -31-32	- - - -	
Northeast Comer, Section 3	31, Ashland Township, N	lewaygo County, Michigan	13	<u> </u>	

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. James H. Mullett 1833 10" Hemlock S36°W 23 Links (15.18')#1 10" Beech N80°E 31 Links (20.46')#2

Winfield S. Merrill (County Surveyor) January 14, 1882 Book A Page's 53 and 54 Stone at corner (set) 24" Pine Stump N55°E 11 Links (7.26') #3

Glen S. Hackbardt P.S. #25844 January 1983 Marker Pipeline N15°E 83.75' #8 Marker Pipeline N20°W 72.70' #10 Power Pole S30°E 69.0' #9 Northeast Corner House S40°W 93.7' #7

Ralph A. Smith RLS #3421 1925 Found Well Point Book 95 Page 36 Telephone Pole N45°E 33.6' #4 Fence Corner N45°W 36.3' #5 14" Locust S45°W 38.3' #6 Northeast Corner House S40°W 99.5'#6

Newaygo Engineering and Survey Company 1982 Found Well Point Northeast Corner New Addition to House \$40°W 93.73' #7 Old witness of 99.5' fits original house corner 4" Pipe Gas Marker N20°E 84.0' #8 Power Pole S30°E 69.0' #9

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR **REESTABLISHING CORNER:**

Found ¾" pipe over Well Point in the centerline of road going South and the centerline of road going North is 6 feet West and the centerline of road going East and West is 2.5 feet South and the condition of the recorded witnesses are: #1 thru #6 gone, #7 thru #10 good condition. Witness #7 has another new addition, old witness of 93.73 feet fits old addition.

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 3/4" pipe and Well Point and set 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Northeast Corner of New Addition to House \$40°W 90.69' #7 4" Pipe Gas Marker N20°E 83.96' Face. #8 Power Pole \$30°E 69.26' Spike in Southwest side of pole. #9 Gas Marker N20°W 72.82' Face. #10		
Signed by Norman L. Ocho	Date September 12, 1996	·
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of I	• •
Approved by Peer Review Group on September 17, 1996	D. M.C.	Revised May 14, 1975 Revised Jan., 198
Norman L. Ochs, County Representative.	6	11041000 0411., 100

L. OCHS

1.40

NORMAN