APR 0 4 1996

1995 Newaygo County Remonumentation Project

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAY: COUNTY

For corners in Newaygo	Located in:	Corner Code#	() = - · ·		113-3-13 S _t
(County)		33			
Public Land Survey	T <u>11N</u> R <u>13W</u>	D-5	rso red	5 21 GM	9 37
	T R T R		~771 st	Conce	Toursel
Property Controlling in Section	STR		vol. $oldsymbol{1}$		
3. Miscellaneous	SK				
Property in Sec.	STR	Regis	ster of Deeds_Stam	ρ&File_Nu	mber
4. Lot No Record	ded Plat		A B C D	E F G H	1 J K L N
5. Private Claims					
			2 - 6 - 5 - 5	3-	1-2-1-1-
I, Norman L. Ochs in a field survey on September 23, 19,95 do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner		nber 23 19_95	3		
		4 7 8	910-	-11-12-	
points mentioned in lines 1 and 2			5	 	
therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in			6 - 10 - 17 -	1615-	1413
			7		1
conformance with the rules of	the Michigan Board of Las	nd Surveyors or by a			
Decree of a Court of Law; established, re-established, monumented, re-monumented,			0 - 19 20	2122-	2324
recovered, found as expressed be	elow:		9	├ ┼╾┼╌├	- - - - -
Note: Not more than 4 o	orners, all in the sam	ie town and range, may be	10 30 29	2827-	2625
recorded on this c		io to wii aira rango, may 20	11	 	
rootided on and c	or milato.		12 31 32	33-34-	3536
1/4 Corner, Section 8, Ashla	nd Twp., Newaygo Co.	, Mi	13		
DESCRIPTION OF ORIGI	NAL MONUMENT AN	D ACCESSORIES AND/OR SU	IBSEQUENT RES	TORATIO	N:
			,		
O. James H. Mullett 1838		Newaygo Engineering and Sun			
' Hemlock N41°W 17Lks (11.22			o. 79127M		
' Elm S10°E 7 Lks (4.62')#2		Found 5/8" rod in mon, box			
RC Sheet		P. Pole N45°W 114.86' #5 St. Sign S25°W 20.90' #6			
ron		31. 31gii 323 W 20.80 #0			
·····					

1" li S.E. Cor. Headwall N45°W 27.1' #3 S.W. Cor. Headwall N45°E 26.8' #4

William Fries Jr. PS #30389 LCRC #1025 June 14, 1990 Found 1" Iron 1.5 ft South of occupied centerline of E-W and 4 ft West of road to the North 5.5 OD S'rly grd. post AZ19° 86.06' (N19°E)#7 P. Pole AZ181° 108.00' (S01°W)#8 6" Ash AZ232° 85.67' (S38°W)#9 P. Pole AZ314° 114.92' (N44°W)#5

Newaygo Engineering and Survey Co. July 27, 1988 Found 5/8" rod in Mon. Box P. Pole N45°W 115.01' #5 Center of St. sign S25°W 20.75 #6

Charles E. Fricke RLS #21781 Liber 356 Pg. 6898 1" Iron 5.5" OD S'rly grd. post AZ19° 86.06' #7 P. Pole AZ181° 108.00' #8 6" Ash AZ232° 85.67' #9 P. Pole AZ314° 114.92' #5

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING **CORNER:**

Found a 5/8" rod, 4 ft long, with old wood stakes with a bed of stones around it in a monument box and the centerline of the East and West road is 1.4 ft North and the centerline of a road going North is 1 ft West and the condition of the recorded witnesses are: #1 thru #4 gone, #5 good condition, #6 gone, #7 thru #9 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 5/8" rod and set a 2 3/4" dia. Harrison cast iron monument in monument box 20" long marked "County Survey"	as a substantial marker for
Removed 5/8" rod and set a 2 ¾" dia. Harrison cast iron monument in monument box 20" long marked "County Survey" the section corner and is accepted as a careful and faithful reestablishment of the original corner.	OF BICKER

P. Pole N45°W 114.86′ #5 Top center of 5.5″ OD S'ly steel grd post of dry hydrant N19°E 85 P. Pole S01°W 108.10′ P.K. nail W.B. Fries tag. #8 6″ Ash S38°W 85.81′ Spike and brass washer on Southeast side		NORMAN L OCHS
Signed by Morman L. Ochs	Date <u>October 2, 1995</u>	SURVEYOR 22439
Approved by Peer Review Group On October 3, 1995 Norman L. Ochs, County Penragentation	Form approved by Michigan State Board of Lar	nd Surveyors, Jan 28, 4971 ND Revised May 14, 1973 Revised Jan., 1983