

MAY 28 1997

COMMISSION

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA H. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

For corners in Newaygo (County)	Located in:	Corner Code#		Linda M. D	Sia
1. Public Land Survey	T <u>11N</u> R <u>13W</u> T R T R T R	E-4	VOL. 1	PAGE 222	
Property Controlling in Section Miscellaneous	STR STR STR				
Property in Sec.	STR	Register	of Deeds_Stamp & F	ile Number	
do hereby certify that under req points mentioned in lines 1 and 1 therefore as required in the curr Department of the Interior, Bure Law and/or that the corner poconformance with the rules of Decree of a Court of Law; establicevered, found as expressed the Note: Not more than 4 recorded on this	in a field survey on October 3 uirements of P. A. 74, Michigan P. 2 above were in conformance with ent manual of survey instructions are of Land Management or by a bints mentioned in lines 3, 4 and the Michigan Board of Land Mich	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a ted, re-monumented,	7	F G II J K L 1	_
East One Quarter Come	r, Section 8, Ashland Towr	nship, Newaygo County, Michigan			

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. James H. Mullett 1838 6" Beech S66°E 29 Links (19.14")#1 6" Beech N45°W 19 Links (12.54')#2

Charles E. Fricke RLS #21781 May 11, 1993 Recorded in Liber 356 Page 6888 Measured 2690.82 feet from the East One Quarter Corner to the Center One Quarter Corner of Section 8

William Fries, Jr. RLS #30389 LCRC #844 June 24, 1988

Set ½" Iron with cap on the East and West ¾ line as evidence by corners F4 and G4. Corner is set at a distance equal to twice the distance between corners F4 and the found 1/8 Corner to the East of F4.

Power Pole with yard lamp AZ19° 125.46' #3 8" Cherry N57°E 54.26' #4

4" Oak S37°E 25,98'#5

36" Maple N04°W 56.28' #6

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1/2" Rod and cap by William Fries, Jr. He set this corner by doubling the distance from the Center Quarter Corner and the East One Eighth Comer of Section 8 and on the East and West One Quarter line as evidence by the West One Quarter Corner and the Center One Quarter Corner of Section 8 and in the fence line (on ground) going North and South and the centerline of the East and West road is 2.5 feet North and in tree row going North and the condition of the recorded witnesses are: #1 and #2 gone, #3 thru #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE L'OCATING THE POSITION OF THE CORNER:

Removed 1/2" Rod and cap and replaced with a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Power Pole with yard light N24°E 125.48' Found nail in West side	of pole, #3
8" Cherry N63°E 54.30' Found spike in West side of tree. #4	,
10" White Oak S33°E 25.96' Found nail and tag #30389 in Northe	east side of tree #5
38" White Oak NO4°, W 56.26' Found nail in root in Southwest side	of tree. #6
N Y Ox O	
Signed by / Orman & Ocho	Date December 3, 1996
Norman L. Ochs	
Surveyor's Michigan License No22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
	Revised May 14, 1975
Approved by Peer Review Group OnDecember 11, 1996	Revised Jan., 1983
Norman L. Ochs, County Representative.	. There is a second of the sec

11.20

