SURVEY & REMONUMENTATION

MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYOR COUNTY REGISTER OF DEEDS LINDA M. BROWN

FILING REQUIREMENT of Act 74, Mich. P.A. 1970 '98 MAR 6 PM 12 34 LAND CORNER RECORDATION CERTIFICATE SECTION

For corners in Newaygo (County)	Located in:	Corner Code #	Linda M	n. Brown
1. Public Land Survey	T <u>11N</u> R <u>13W</u> T R T R	F-5	vol. 2	65
Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R S T R		Register of Deeds Stamp & Fil	e Number
4. Lot No, Reco	rded Plat		A B C D E F G H I	J K L M
do hereby certify that under req points mentioned in lines 1 and therefore as required in the curr Department of the Interior, Bure Law and/or that the corner po conformance with the rules of	, in a field survey on <u>Septem</u> uirements of P. A. 74, Michigan P. 2 above were in conformance with ent manual of survey instructions au of Land Management or by a bints mentioned in lines 3, 4 and the Michigan Board of Land blished, re-established, monumen	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a	3 4 7 8 9 10 - 5 6 18 17 16 15 - 7 8 19 20 21 22	
Note: Not more than 4 recorded on this c	corners, all in the same to	own and range, may be	9 10 30 - 29 - 28 - 27 - 11 12 - 31 + 32 - 33 - 34 -	
South One Quarter Corner	Section 9. Ashland Township.	Newayon County Michiga	n. 12 1 1 1 1 1 1 1 1 1	ليلي

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. James H. Mullett 1838 12" Hemlock S55°W 17 Links (11.22')#1 12" Hemlock N65°E 8 Links (5.28')#2

Newaygo Engineering and Survey Company August 17, 1983 Drawing Number 83144B&M Found 1" Square Bolt in monument box

William Fries, Jr. R.L.S. #30389 June 1990 Found 1 1/8" Square Bolt 18" White Pine N19°E 75.07' #9

Newaygo County Road Commission Sheet 1" Iron Project Marker S65°W 49.3' #3 Northeast Corner School Foundation S29°W 104.26 #4 Service Pole \$29°E 82.2' #5 "X" East Curb S66°E 51.6' #6 "X" West Curb S65°W 51.7" #6 18" White Pine East 93.6' #8

OVER &

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1/2" Square Bolt 16" long in monument box in centerline of East and West blacktop road and in centerline of blacktop road going South. The centerline of gravel road going North is 4 feet West. The condition of the recorded witnesses are: #1 thru #3 gone, #4 good condition, #5 gone, #6 thru #8 good condition, #9 gone, #10 and #11 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 11/2" Square Bolt and set a 23/4" diameter Harrison cast iron monument 18" long marked "County Surveyor" in monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner. or elevier

"X" East Curb S66°E 51.6' on top. #6	
"X" West Curb S80°W 51.75' on top. #7	
32" White Pine N81°E 93.61' Found tag #30389 in Sout	h side of tree. #8
Power Pole S51°W 45.87' Found tag #30389 in Northw	est side of pole. #10
Telephone pedestal Westerly Bolt top N30°W 55.73' #1	1
Project Marker S60°W 60.98'	
Signed by //Oman A. Chs	Date <u>October 10, 1997</u>
Norman L. Ochs Survevor's Michigan License No. 22439	Form approved by Michigan State Board

of Land Surveyors, Jan 28, 1971

Approved by Peer Review Group on October 14, 1997 Norman L. Ochs, County Representative.

Northeast Corner School Foundation S33°W 103.96' #4

Revised May 14, 1975 Revised Jan., 1983

NORMAN L. OCHS LAND URVEYOR 22439

PED LAND

A. Description (cont.)

William Fries, Jr. R.L.S. #30389
1993 Found 1 1/8" Square Head Bolt
18" White Pine N19°E 75.07' #9
29" White Pine N73°E 93.92' #8
Power Pole S46°W 45.87' #10
"X" West end top of Curb S35°E 51.74' #7
Telephone Pedestal Westerly Bolt Top N41°W 55.74' #11

.