

MAY 2,8 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

For corners in				0 2
Newaygo	Located in:	Corner Code #		Linda M. Brow
(County)	•		•	- 1
1. Public Land Survey	T <u>11N</u> R <u>13W</u> T R T R	<u>G-3</u>	4	004
2. Property Controlling	TR STR		VOL. $oldsymbol{1}$	PAGE 224
in Section	STR	· · · · · · · · · · · · · · · · · · ·		
3. Miscellaneous Property in Sec.	S IR STR	· Regi	ster of Deeds Sta	amp & File_Number
				EFBHIJK LM
4. Lot No, Record	ded Plat		2	
J. Filvate Olamis		.	3 5-	
. Norman I Ocho	in a field survey on <u>November</u>	1 10.08		
do hereby certify that under requ	irements of P. A. 74, Michigan P./	A. of 1970, the corner	5	
points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States			6 -18	-16151413
Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in			7	- - - - -
conformance with the rules of	nts mentioned in lines 3, 4 and the Michigan Board of Land	d 5 above were in Surveyors or by a	8 -1920-	-21222324-
Decree of a Court of Law, estable	ished, re-established, monument	ted, re-monumented,	0	. - - - - - -
recovered, found as expressed be	BIOW:		10 -30 29 -	
	•	town and range, may be	<u>'</u>	
recorded on this	certificate.	-	12 -3132-	- 33 34 35 36-
Southeast Corner, Section 4, Ashland Township, Newaygo County, Michigan				
A. DESCRIPTION OF O	RIGINAL MONUMENT A	ND ACCESSORIES AND/O	R SUBSEQUEN	T RESTORATION:
G.L.O. James H. Mullett 183 10" Aspen N25°W 24 Links (18" Pine N64°E 15 Links (9.9 Measured 79.90 Chains (527 Corner of Section 4 to the So 4 and measured 80.04 Chair Southwest Corner of Section	(15.84')#1 90')#2 73.40') from the Southwest outheast Corner of Section as (5282.64') from the	of Section 4 to the Southe Chains (2669.70') from th One Quarter Corner of Se	o, 1882 2604.36') from the east Corner of Sect e Southwest Corne ection 3.	South One Quarter Corner ion 4 and measured 40.45 er of Section 3 to the South
of Section 3 and measured 3 and measured 40.02 Chains	9.95 Chains (2636.70') from (2641.32') from the Southwe	the South One Quarter Corner o st Corner of Seciton 3 to the Sou	f Section 4 to the S ath One Quarter Co	Southeast Corner of Section 4 Friner of Section 3.
B. DESCRIPTION OF C REESTABLISHING COR		ND AND/OR METHOD APP	PLIED IN RESTO	DRING OR
West road. I measured 2614 feet from the Southeast Corr One Quarter Corner of Section	4.58 feet from the South One ner of Section 4 to the South (on 3 to the South One Quarte	Set corner in fence line on groun Quarter Corner to the Southeast One Quarter Corner of Section 3 or Corner of Section 4 and meast on of the recorded witnesses are:	: Corner of Section and measured 528 ured 2627.29 feet fi	4 and measured 2668.32 32.90 feet from the South
C. DESCRIPTION OF N LOCATING THE POSITI		ER AND ACCESSORIES ES	TABLISHED TO	PERPETUATE
	ast iron monument 20" long m ithful reestablishment of the o	narked "County Surveyor" as a st riginal corner.	ubstantial marker fo	or the section corner and is
8" Ash N78°E 83.70' Set spi 6" Red Pine N20°E 64.07' S				
Signed by / Dimay	nd, Ocho	Date Novembe	er 30, 1996	
Norman L. Ochs Surveyor's Michigan License No. 22439 Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975				
Approved by Peer Review Group Norman L. Ochs, County Repres			15.	Revised Jan., 1983
n. 20.	•	A TILL WAR	70	

NORMAN L. OCHS