

WAR 0 2 1999

1998 Newaygo County Remonumentation Project, 99 FEB 17 PM 3 33

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74 Mich PA 1970

SECTION	FILING REQUIREMENT of Act 74, Mich. P.A. 1970 Linda M. Brown			
For corners in Newaygo (County)	Located in:	Corner Code #		
Public Land Survey	T <u>11N</u> R <u>13W</u> T R T R	<u>G-10</u>	vol. 2	162
Property Controlling in Section Miscellaneous	STR_ STR_ STR	-	*	
Property in Sec.	STR		egister of Deeds Stamp 8	File Number
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curr Department of the Interior, Bure Law and/or that the corner poconformance with the rules of Decree of a Court of Law; estab recovered, found as expressed by	in a field survey on Novemb lirements of P. A. 74, Michigan P 2 above were in conformance with ent manual of survey instructions au of Land Management or by a ints mentioned in lines 3, 4 an the Michigan Board of Land lished, re-established, monument below: corners, all in the same to	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a state, re-monumented,	1 2 6 5 4 - 3 4 7 8 9 - 5 - 18 17 - 16 - 7 - 19 - 20 - 21 - 9 - 30 - 29 - 28	G H I J K L I 3 - 2 - 1 - 1 - 10 - 11 - 12 - 1 - 15 - 14 - 13 - 1 - 22 - 23 - 24 - 1 27 - 26 - 25 - 1 - 34 - 35 - 36 - 36
East One Quarter Corner, So	ection 28, Ashland Township,	Newaygo County, Michigan.	$\frac{12}{13}$ $\frac{31}{32}$ $\frac{33}{33}$	1 1 1

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. James H. Mullett 1838 6" Beech N68°E 8 Links (5.28')#1 12" Beech S29°W 25 Links (16.5')#2

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found nothing. Established corner equal distance and on line between the Southeast Corner and the Northeast Corner. The remnants of This position fits existing occupation. The condition of the recorded witnesses are: #1 and #2 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

marker for the section corner and is accepted as a careful	anced County Surveyor with storie pile around as a substantial and faithful reestablishment of the original corner.
20" Beech (blazed) S25°E 12.72' Set spike with tag #22439 18" Maple (blazed) N62°E 8.00' Set spike with tag #22439 i 10" Cherry (blazed) S28°W 33.64' Set spike with tag #2243 10" Maple (blazed) N77°W 45.90' Set spike with tag #2243 Signed by	in Westerly side of tree. 39 in East side of tree.
Norman L. Ochs	
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975
Approved by Peer Review Group On <u>December 22, 1998</u> Norman L. Ochs, County Representative.	Revised Jan., 1983



