APR 2 4 1995

COMMISSIEN 4 NEWAYGO COUNTY REMONUMENTATION PROJECT

100	COOMIT	ICHIOMOTHEM TITE TON	22100000
			3. 3
AND	CORNER	RECODERATION CERTIFIC	[™] ATE

For corners in	Filing Requir	rement of Act 74, Mich. P.A.	1970 V OL	001 PAGE	81
Newaygo	_ Located In:	Corner Code ##		NEWAVAA	
(County)				NEWAYOD (REGISTER O	JORNE - COUNTY
1. Public Land Survey	т <u>11N</u> в <u>13W</u>	<u>L-7</u>	•	MARLENE TO	ELNEFDS UUCUUU
	T R				
•	T R T R		' 95	5 MAR 14 P	M 3 53
2. Property Controlling	S R				
in Section	S T R		\mathcal{I}	Narlone -	Tournel
Miscellaneous Property in Sec.	S T R S T R		Register of Dee	ds Stamp & Fil	ie Number
r roperty in oco.	· · · · · · · · · · · · · · · · · · ·				
			— АВС	DEFGH	
5. Private Claims	· · · · · · · · · · · · · · · · · · ·		2 6	ŢŢŢ	Ĭ, i
			3		
Marana T. Oaka		04	4	- 8 - 9 10	11-12
Norman L. Ochs		of 1970, the corner points mentione	. 5	 	
in lines 1 and 2 above were in c	onformance with regulations an	id rules therefore as required in th	ne 0 18	-17-16-15-	14-13
		tment of the Interior, Bureau of Lan er points mentioned in lines 3, 4 and		+ + + +	
above were in conformance with	the rules of the Michigan Board o	of Land Surveyors or by a Decree of	a	-20 -2122	23 24
Court of Law; established, re- expressed below:	established, monumented, re-r	monumented, recovered, found a	10 30	29 - 25 27	26 25
NOTE: Not more than 4 core	ners, all in the same town ar	nd range, may be recorded	11		
on this certificate.	riam 10 Aabilam di	Norrerra Co	MT 12 31	.32 33 34-	35-36
SN:1/4 Corner, Sect A. Description of original mo			13	4 1 1 1 1 1 1	
		9			
G.L.O. James H. Mullett 1 18" Pine S55°W 18 1ks. (1		Lyle S. Shepherd R.L.S. #50 Book 84 Page 19	13 April 1949		
24" Pine N54"W 15 lks. (9	•	Measured 2650.80 feet from	the S. 1/4 Cor.	to	
	•	the S.W. Cor. of Sec. 13.	,		
Delos G. Anderson (Co. Su	- ,		3:1!	130001	
August 1896 Book A, Page Measured 40.36 ch. (2663.			alisbury R.L.S. i	13594	
the N. 1/4 Cor. of Sec. 2			703	OVER	>
from the N. 1./4 Cor. to	the C. 1/4 of Sec. 24.				
B. Description of corner evid	ence found and/or method a	applied in restoring or reestabli	shing corner:		
Found 1/2" pipe nipple .3	0 foot long and the Condi	tion of recorded witnesses	are: #1 THRU #3	Gone, #4 thru	#6 Good
Condition, #7 thru #9 Gon	e.				
		, ,			
				•	ů.
				:	
					-
C. Description of monument to	for corner and accessories e	stablished to perpetuate locati	ng the position of	the corner:	
	.		,		
		t iron Monument 20" long ma			
marker for the section co Guy Pole S60°E 53.57' Spi		careful and faithful reest	adiisament of th	e original to	cuer.
Zephyr Sign (Face) @N.E.			4	THE OF MIC	
N.E. Cor. Building S45°W	89.38' ‡ 6		· **	NORMAN	2 ~ 72
Top C.L. of C.B. S40°W 39				L OCHS	* 2
24" Maple S75'E 81.33' P. 18" Maple S20'E 93.32' P.				SURVEYO	R /5
S.E. Cor. of Wood Buildin	g N45°W 61.80°		4	22439	J.S.F
N.E. Bolt on Sign Base S2)	•	DIAND	20 A Tage
Mon	7/9.1	Norte	ember 10,199	4 MANAGEMENT	Chine.
Signed by Norman I Oo	the				
Surveyor's Michigan License N		FOR	M APPROVED BY MICHIGAN STA	ATE BOARD OF LAND SUR!	VEYORS, JAN. 28, 19
	Review Group on De		•		REVISED JAN., 19
rman L. Ochs. Co	ounty Representati	ive, 1/1 X 64			

A. Description.....(Continued) Surveyor? N.E. Corner of Block 1 of "Squier and Burril's Addition" to the Village of Grant is the N. 1/4 Cor. of Sec. 24, TllN R13W, City of Grant, Newaygo County, Michigan. Patrick A. Salisbury R.L.S. #13594 February 22, 1972 See survey recorded in Series E, No. 3425 P.K. Nail in intersection of M-37 and State Road Measured 2674.18 feet from the S. 1/4 Cor. to the C. 1/4 Cor. of Sec. 13. Newaygo Engineering and Survey Co. 1979 Recorded in Series J, No. 6951. P.K. Nail in intersection of M-37 and State Road Measured 2658.36 feet from the N. 1/4 Cor. to the C. 1/4 Cor. of Sec. 24. Newaygo Engineering and Survey Co. January 28, 1980 Drawing No. 80003B Found P.K. Nail P. Pole N45 W 33.48' Spike in N.E. side of pole #3 Guy Pole S60°E 53.64' Spike in Southerly side of pole #4 Zephyr Sign (Face) @ N.E. Cor. of sign S30 W 56.91 #5 Newaygo Engineering and Survey Co. July 22, 1981 Found P.K. Nail - Reset 1/2" Pipe over P.K. Nail. Pipe is +- 0.30 feet long. Put blacktop around pipe. P. Pole N45°W 33.48' Spike in N.E. side of pole #3 Guy Pole S60°E 53.64' Spike in Southerly side of pole #4 Zephyr Sign (Pace) @ N.E. Cor. of sign S30°W 56.91' \$5 Newaygo Engineering and Survey Co. May 18, 1984 Drawing No. 84017B Pound 1/2" Pipe P. Pole N45 W 33.48 #3 į. Guy Pole S60°E 53.64° #4 Zephyr Sign (Face) @ N.E. Cor. of sign S30 W 56.94' #5 Newaygo Engineering and Survey Co. December 12, 1985 Drawing No. 85154B Found P.K. Nail P. Pole N45°W 33.48' Spike in N.E. side of pole #3
Guy Pole S60°E 53.64' Spike in Southerly side of pole #4 Zephyr Sign (Face) @ N.E. Cor. of sign S30°W 56.94' #5 Newaygo Engineering and Survey Co. May 22, 1986 Drawing No. 86081LS Found 1/2" Pipe Coupling 3" long Newaygo Engineering and Survey Co. December 12, 1986 Drawing No. 86266B

P. Pole S55°E 53.50' Nail in S.W. side of pole #4
N.E. Cor. Bldg. S60°W 89.40' #6
On C.L. Bit North and South 0.50' North C.L. Bit. East and West

Found 1/2" Nipple

Charles E. Fricke R.L.S. #21781 November 11, 1991 See survey recorded in Liber 353 Pages 1165 thru 1168. P. Pole S45°W 33.48′ #3
Guy Pole S60°E 53.64′ #4
Sign S30°W 56.94′ #5

Newaygo Engineering and Survey Co. 1992
Found P.K. Nail and tag at intersection of M-37 (Lake Street) and State Road
Tel. Pole and Street Light N45°E 35.14' Spike in S.W. side of pole \$7
Tel. Pole and P. Pole S40°E 50.42' Nail in East side of pole \$8
Top C.L. of C.B. S40°W 44.14' \$9